

(08/11/13)

wef

REF:

C4/LPC 23004.750/R ya3

3820

ASS. REC. BY:

ASSIGNMENT

COE-2031/JAN

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SOV 5822 Z

at Workshop m/s AUTOWORLD

of GA, LOK yamh wan

Insured: LPC

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

JIANIN

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

91K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 61K

Veh No:

SDV 5822 Z

Yr Regn:

2012 / JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MECEMS BENZ C180 COMP c.c 1597

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading:

160970

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W20 204 045 2A 639 471

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/05/23

D.O.I.

10/05/23

Survey held at

AUTOWORLD

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Estimate



AUTOWORLD BODYWORKS PTE LTD

Email: claims@autoworldcare.com.sg

LONPAC INSURANCE BHD

Please arrange to survey at
9A LOK YANG WAY SINGAPORE 628628

Your Reference Vehicle No:
GBH6064K

Our Reference: SDV5822Z
Date: 10/05/2023
Vehicle No: SDV5822Z
Model: MERCEDES C180
Year:
Date of Loss: 05/05/2023

Qty	Description	List Price	Remarks
1.00	RH SIDE HEADLAMP <i>brb</i>	\$ 1,515.00	
1.00	FENDER RH SIDE <i>fern</i>	\$ 1,257.80	
1.00	SIDE RETAINER RH <i>rw</i>	\$ 65.78	

TOTAL: \$ 2,838.58
LESS 10 %: \$ 283.86
\$ 2,554.72 ✓

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	TO SPRAY FRONT BUMPER, FENDER AND BONNET	\$ 600.00	<i>550</i>
1.00	TO REMOVE FRONT BUMPER AND FENDER TO REPLACE ACCIDENT PARTS	\$ 500.00	<i>450 1000</i>

TOTAL: \$ 1,100.00
SUBTOTAL: \$ 3,654.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

Rane
Hp 900 10068
5 days
L/S
10/05/23 @ 1455
Resy after repair

Estimate



AUTOWORLD BODYWORKS PTE LTD

Email: claims@autoworldcare.com.sg

LONPAC INSURANCE BHD

Please arrange to survey at
9A LOK YANG WAY SINGAPORE 628628

Our Reference: SDV5822Z

Date: 10/05/2023

Vehicle No: SDV5822Z

Model: MERCEDES C180

Year:

Date of Loss: 05/05/2023

Your Reference Vehicle No:
GBH6064K

SUPPLEMENTARY ITEM

Qty	Description	Unit Price	Remarks
-----	-------------	------------	---------

1	FRONT BUMPER <i>De ✓</i>	\$1,400.00	
---	--------------------------	------------	--

1400

10%

1260

TOTAL: \$ 1,400.00

2554.72

1260.00

1000.00

4814.72

20%

3851.77

48- \$3,850 / 5 days