

# ADVANCE AUTO GARAGE

|                        |                     |         |            |
|------------------------|---------------------|---------|------------|
| TO                     | : LONPAC            | DATE    | : 2/5/2023 |
| <b>VEHICLE DETAILS</b> |                     |         |            |
| VEHICLE NO             | : SNK526B 2019 NOV  | Ezlyna. |            |
| VEHICLE MODEL          | : NISSAN SYLPHY     |         |            |
| CHASSIS NO             | : MNTBBAB17Z0035517 |         |            |

## CLAIM DETAILS: PARTS

|    | ITEMS                                    | QTY | UNIT PRICE | TOTAL     |
|----|------------------------------------------|-----|------------|-----------|
| 1  | REAR BUMPER <i>Deband</i>                | 1   | \$ 683.60  | \$ 683.60 |
| 2  | REAR BUMPER SIDE HOLDER <i>3 new</i>     | 2   | \$ 35.20   | \$ 70.40  |
| 3  | REAR BUMPER REFLECTOR                    | 2   | \$ 47.10   | \$ 94.20  |
| 4  | REAR BUMPER CENTRE <i>Sponge 3 new</i>   | 1   | \$ 88.10   | \$ 88.10  |
| 5  | REAR BUMPER SIDE SPONGE                  | 2   | \$ 45.00   | \$ 90.00  |
| 6  | REAR BUMPER IMPACT BRACKET               | 2   | \$ 91.70   | \$ 183.40 |
| 7  | TAILLAMP <i>crackd. LH</i>               | 2   | \$ 240.50  | \$ 481.00 |
| 8  | TAILLAMP PANEL <i>Deband New</i>         | 2   | \$ 168.50  | \$ 337.00 |
| 9  | REAR END PANEL <i>Deband</i>             | 1   | \$ 491.80  | \$ 491.80 |
| 10 | REAR END PANEL TOP GARNISH <i>Deband</i> | 1   | \$ 85.40   | \$ 85.40  |
| 11 | REAR END PANEL ANTENNA SENSOR <i>New</i> | 1   | \$ 68.90   | \$ 68.90  |
| 12 | BOOTLID <i>Deband</i>                    | 1   | \$ 850.90  | \$ 850.90 |
| 13 | BOOTLID LOCK <i>2nd</i>                  | 1   | \$ 115.70  | \$ 115.70 |
| 14 | BOOTLID WEATHERSTRIPE <i>new</i>         | 1   | \$ 91.10   | \$ 91.10  |
| 15 | BOOTLID LOWER MOULDING <i>3 new</i>      | 1   | \$ 257.40  | \$ 257.40 |
| 16 | BOOTLID UPPER MOULDING <i>3 new</i>      | 1   | \$ 357.40  | \$ 357.40 |
| 17 | BOOTLID REFLECTOR <i>new</i>             | 2   | \$ 201.10  | \$ 402.20 |
| 18 | NISSAN LOGO <i>3 new</i>                 | 1   | \$ 55.40   | \$ 55.40  |
| 19 | SYLPHY WORDING <i>3 new</i>              | 1   | \$ 65.90   | \$ 65.90  |
| 20 | SPARE TYRE PANEL TOP COVER <i>3 new</i>  | 1   | \$ 240.40  | \$ 240.40 |
| 21 | SPARE TYRE PANEL TOP SPONGE              | 1   | \$ 295.80  | \$ 295.80 |
| 24 | REAR EXHAUST PIPE <i>3 new</i>           | 1   | \$ 740.80  | \$ 740.80 |
| 25 | REAR EXHAUST PIPE MOUNTING               | 1   | \$ 35.40   | \$ 35.40  |

2589.20

2330.28

TOTAL PRICE: \$ 6,182.20  
 LESS 10% \$ 618.22  
 SUB TOTAL PRICE: \$ 5,563.98

## SPECIAL NETT ITEMS

|   | ITEMS                                       | QTY   | UNIT PRICE  | TOTAL       |
|---|---------------------------------------------|-------|-------------|-------------|
| 1 | REAR NUMBER PLATE <i>3 new</i>              | 1     | \$ 30.00    | \$ 30.00    |
| 2 | REAR NUMBER PLATE HOLDER <i>3 new</i>       | 1     | \$ 30.00    | \$ 30.00    |
| 3 | REAR BUMPER CLIPS <i>new</i>                | 1 SET | \$ 50.00    | \$ 50.00    |
| 4 | REAR BUMPER LOWER SPOILER <i>Deband</i>     | 1     | \$ 1,000.00 | \$ 1,000.00 |
| 5 | REVERSE SENSOR <i>2nd</i>                   | 1 SET | \$ 280.00   | \$ 280.00   |
| 6 | REAR END PANEL TOP GARNISH CLIPS <i>new</i> | 1 SET | \$ 20.00    | \$ 20.00    |
| 7 | REAR END PANEL SEALANT <i>new</i>           | 1 SET | \$ 60.00    | \$ 60.00    |
| 8 | BOOTLID TOP SPOILER <i>crackd</i>           | 1     | \$ 800.00   | \$ 800.00   |
| 9 | REAR CAMERA <i>new</i>                      | 1     | \$ 480.00   | \$ 480.00   |

TOTAL: \$ 2,750.00

1710

# LABOUR

|        | JOB                                        | PRICE       | ADJUSTED COST | APPROVED |
|--------|--------------------------------------------|-------------|---------------|----------|
| 1      | PANEL BEATING, REMOVE AND REFIT PARTS      | \$ 1,400.00 | 800.          |          |
| 2      | SPRAY PAINTING TO AFFECTED AREA            | \$ 1,200.00 | 1800.         |          |
| 3      | WIRING CHECK                               | \$ 100.00   | 30.           |          |
| 4      | TO REMOVE REVERSE SENSOR                   | \$ 100.00   | 50.           |          |
| 5      | TO REMOVE AND REFIT BOOTLID CAMERA         | \$ 100.00   | 50.           |          |
| 6      | TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS | \$ 150.00   | 40.           |          |
| 7      | TO APPLY TUFF COAT                         | \$ 150.00   | 60.           |          |
| 8      | TO REMOVE REAR EXHAUST PIPE                | \$ 150.00   | X             |          |
| 9      | TO TRANSFER BOOTLID FITTINGS               | \$ 150.00   | 60.           |          |
| TOTAL: |                                            | \$ 3,500.00 |               |          |

## ESTIMATE REPORT

TOTAL PARTS COST: \$ 8,313.98

TOTAL LABOUR COST: \$ 3,500.00

TOTAL REPAIR COST: \$ 11,813.98

1790.

total 5930.28  
L/s: 4.7K

4.7K

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: