

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004757/UNP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00192012200

Claimant Vehicle No : SKT6572R **Insured Vehicle No :** SJN5404T

Date of Loss: 18/03/2023 Nature of Claim: TP Claim No: SNM23D202100/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT6572R**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B3521572

Reg. Date: 18/06/2015 (Man. Year: 2015) Chassis No: RU11021556

Colour: Blue Odometer: 166359 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,215.04	3,258.48	7,956.56	70.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,470.00	750.00	3,720.00	83.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,685.04	4,008.48	11,676.56	74.44
Approved Total (Overridden) (\$\$)		3,200.00		
Nett Amount (\$\$)	15,685.04	3,200.00	12,485.04	79.60

INSPECTION

Date of Assignment: 10/05/2023

Date Inspected: 10/05/2023 Inspected At:

1 KAKI BUKIT AVE 6
#01-73, AUTOBAY @KAKI BUKIT
SINGAPORE 417883
Repairer:SPEEDWERKZ PTE LTD (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT6572R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	1,569.60 FL	*- FL
2	1		*FRONT BONNET LOCK	Not Necessary	265.80 FL	*- FL
3	1		*FRONT HEADLAMP LH	Holder Cracked	1,952.20 FL	*1,859.00 FL
4	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	169.30 FL	*- FL
5	1		*FRONT BUMPER	Distorted	1,289.60 FL	*761.00 FL
6	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	354.20 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER LH	Grazed	99.60 FL	*99.60 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	685.50 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER	N/s Bent	70.00 FL	*35.00 FL
10	1		*FRONT BUMPER LOWER LIP	Grazed	945.50 FL	*420.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	485.20 FL	*- FL
12	1		*FRONT BUMPER SPONGE	No such part	133.10 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Repair	998.50 FL	*- FL
14	1		*FRONT FENDER LH	Bent	785.20 FL	*485.10 FL
15	1		*FRONT FENDER COWLING LH	Twisted	158.20 FL	*158.20 FL
16	1		*FRONT FENDER WHEEL ARCH LH	Distorted	325.00 FL	*180.20 FL
17	1		*FRONT SHOCK ABSORBER LH	Not Necessary	374.40 FL	*- FL
18	1		*FRONT KNUCKLE ARM LH	Not Necessary	390.20 FL	*- FL
19	1		*FRONT WHEEL BEARING LH	Not Necessary	147.70 FL	*- FL
20	1		*FRONT WHEEL BEARING HUB LH	Not Necessary	245.00 FL	*- FL
21	1		*FRONT LOWER ARM LH	Not Necessary	350.00 FL	*- FL
22	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*FRONT SPORT RIM LH	Repair	1,200.00 FS	*- FS
25	1		*FRONT TYRE LH	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,573.80	4,058.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,358.76	799.62
Total Parts (\$\$)	11,215.04	3,258.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	150.00	20.00
2	TO APPLY ANTI RUST	New	150.00	30.00
3	REMOVE AND REPLACE FRONT SUSPENSION	New	650.00	0.00
4	TO CHECK WHEEL ALIGNMENT	New	120.00	0.00
5	TO KNOCK DENT ON DAMAGE PORTION	New	1,800.00	300.00
6	TO SPRAY PAINTING AND ETC	New	1,600.00	400.00
Gross Labour Cost (S\$)			4,470.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >