

NOT AUTHORIZED
 L1 Pny 82700/r
 Recovery After Paint
 4 days



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO : INDIA INTERNATIONAL INSURANCE

ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO.: FBR7378X

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : ZULKINIA BIN SUKIMAN

CONTACT :

ADDRESS :

LICENSE NC SLF5484E TRANS. :

CHASSIS NO :

MAKE / MODEL : PEUGEOT 5008

ENGINE NO :

OWNER'S INSURER HL ASSURANCE

JOB-CODE : TP

S/A : JOEY

ACCIDENT DATE : 25-Apr-23

CLAIM DETAIL

MATERIALS

			QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1	REAR BUMPER	850 BULUM	1.00	1350.00	10.00	1215.00	Y	✓
2	REAR BUMPER BRACKET LH	R	1.00	80.00	10.00	72.00	Y	X
3	REAR BUMPER BRACKET RH	R	1.00	80.00	10.00	72.00	Y	X
4	REAR BUMPER RETAINER LH	R	1.00	80.00	10.00	72.00	Y	X
5	REAR BUMPER RETAINER RH	R	1.00	80.00	10.00	72.00	Y	X
6	TAILGATE	R	1.00	1452.00	10.00	1306.80	Y	✓
7	TAILGATE STOPPER	R	1.00	80.00	10.00	72.00	Y	X
8	TAILGATE OUTER HANDLE	R	1.00	280.00	10.00	252.00	Y	X
9	TAILGATE EMBLEM PEUGEOT	R	1.00	75.00	10.00	67.50	Y	X
10	TAILGATE LOGO	R	1.00	112.00	10.00	100.80	Y	X
11	TAILGATE EMBLEM 5008	R	1.00	52.00	10.00	46.80	Y	✓
12	TAILGATE RUBBER BEADING	R	1.00	128.00	10.00	115.20	Y	X
13	TAILGATE LOCK	R	1.00	85.00	10.00	76.50	Y	X
14	TAILGATE LOCK CATCH	R	1.00	155.00	10.00	139.50	Y	X
15	TAILGATE INNER TRIM	R	1.00	243.00	10.00	218.70	Y	X
16	TAILLAMP RH	R	1.00	543.00	10.00	488.70	Y	X

17	REAR END PANEL	1.00	680.00	10.00	612.00	Y	<u>RX</u>
18	REAR BUMPER REINFORCEMENT	1.00	485.00	10.00	436.50	Y	<u>NIPX</u>
19	TOWING COVER	<i>Sn</i> 1.00	46.00	10.00	41.40	Y	<u>X</u>
20	NO. PLATE LAMP	<i>Sn</i> 1.00	138.00	10.00	124.20	Y	<u>X</u>
21	REAR BUMPER LAMP RH	<i>Sn</i> 1.00	334.00	10.00	300.60	Y	<u>X</u>
22	REAR BUMPER SPONGE <i>120</i>	1.00	175.00	10.00	157.50	Y	<u>EMA ✓</u>
23	REAR BUMPER SWITCH OPEN	<i>Sn</i> 1.00	305.00	10.00	274.50	Y	<u>X</u>
24	REAR END PANEL INNER GARNISH	<i>Sn</i> 1.00	138.00	10.00	124.20	Y	<u>X</u>
25	REAR SEAT RH	<i>Sn</i> 1.00	2650.00	10.00	2385.00	Y	<u>X</u>
TOTAL (PARTS) :			9826.00		8843.40		

SPECIAL NETT ITEM

1	REVERSE SENSOR	1.00	280.00	0.00	280.00	Y	<u>X <i>Sn</i></u>
2	REAR BUMPER CLIPS	<i>nn</i> 1.00	50.00	0.00	50.00	Y	<u>—</u>
3	REAR END PANEL SEALANT	<i>n</i> 1.00	180.00	0.00	180.00	Y	<u>X <i>nn</i></u>
4	REAR END PANEL GARNISH CLIPS	<i>nn</i> 1.00	50.00	0.00	50.00	Y	<u>X</u>
5	TAILGATE INNER TRIM CLIPS	<i>nn</i> 1.00	50.00	0.00	50.00	Y	<u>X</u>
6	REAR NO. PLATE	<i>Sn</i> 1.00	50.00	0.00	50.00	Y	<u>X</u>
TOTAL (PARTS) :			660.00		660.00		

LABOUR

1	STRENGTHEN & PANEL BEAT ACCIDENT AREA	1.00	1500.00	0.00	1500.00	Y	<u><i>500l</i></u>
2	RESpray ACCIDENT AREA& SPARE TYRE COMPARTMENT	1.00	1500.00	0.00	1500.00	Y	<u><i>500l</i></u>
3	R&R TAILGATE COMPONENTS	1.00	180.00	0.00	180.00	Y	<u><i>60l</i></u>
4	R&R SPARETYRE BOARD, CARPET & TRIM	1.00	180.00	0.00	180.00	<i>nn</i>	<u>X</u>
5	CHECK & REPAIR WIRING SYSTEM	1.00	120.00	0.00	120.00	Y	<u><i>20l</i></u>
6	RESpray TUFF KOTE ON ACCIDENT AREA	1.00	280.00	0.00	280.00	Y	<u><i>30l</i></u>
7	RESET AUTO SWITCH SYSTEM	1.00	280.00	0.00	280.00	Y <i>nn</i>	<u>X</u>
8	R&R REAR SEAT CARPET & TRIM	1.00	180.00	0.00	180.00	Y <i>nn</i>	<u>X</u>

TOTAL (LABOUR) : 4220.00 4220.00

TOTAL PARTS & LABOUR 14706.00 13723.40

EXCESS : : S\$ _____

NO. OF DAY : 4 days

RE-SURVEY : ~~BEFORE~~ / AFTER PAINTING

PART ~~BY~~-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 9 / /

SURVEY BY : Hennerh

CONTACT N : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: