



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 2044H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	BUCKLED	1,038.00	1,038.00
2	FRONT BUMPER RETAINER @\$21.00	SERVICEABLE	42.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	485.00	-
1	FRONT BUMPER BELOW GRILLE	SERVICEABLE	252.30	-
1	FRONT BUMPER CENTRE GRILLE	CRACKED	445.00	445.00
1	FRONT BUMPER LOGO	NECESSARY	48.00	48.00
2	FRONT BUMPER BELOW FOG LAMP @\$185.50	SERVICEABLE	371.00	-
1	FRONT BONNET LID	TO REPAIR SEE LABOUR	1,221.00	-
2	FRONT HEADLAMP @\$914.50	MTG CRACKED	1,829.00	1,829.00
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	434.00	-
2	FRONT BUMPER GRILLE CHROME @\$164.00 (ADDITIONAL)	N/S DENTED	328.00	164.00
2	FRONT BUMPER BELOW CORNER COVER @\$31.00 (ADDITIONAL)	NECESSARY	62.00	62.00
1	FRONT SUPPORT PANEL SEAL PLATE (ADDITIONAL)	DISTORTED	86.00	86.00
	LESS 20% DISCOUNT		-1,328.26	-734.40
			5,313.04	2,937.60
<b><u>SPECIAL NETT ITEMS</u></b>				
2	NUMBER PLATE WITH CASING (SN)	SERVICEABLE	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	SET FRONT BUMPER GRILLE CLIP (SN)	NECESSARY	30.00	30.00
2	SET FRONT HEADLAMP CLIP (SN)	NOT NECESSARY	40.00	-
			170.00	80.00
<b><u>LABOUR</u></b>				
	TO CHECK UP ELECTRICAL WIRING.		180.00	20.00
	TO RESPRAY PAINTING & ETC.		600.00	400.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEAT, REMOVE AND REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BONNET LID AND FRONT LH FENDER.		800.00	400.00
			1,580.00	820.00
GRAND TOTAL			7,063.04	3,837.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/LIP23004768/Kny3m4

MARKET VALUE: \$43,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$19,124.00=NETT VALUE: \$23,876.00

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.