

ASS. REC. BY:

REF:

CIP / 23004768 / Kny3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 843K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLB 2044H Yr Regn: 03.16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Merida 3 c.c. 1498Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 244540 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 6B M 42A 8G 0330031Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 6 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 15/1/23 D.O.I. 10/5/2023

Survey held at _____

Des. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 EST NOT ready, wksp will email GIA over.

5/6 11Rm 831001 Contw 16/6/23 (Red, \$ 3922.24, 55%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 FAX : 64550902

The Motor Claims Dept.

LIBERTY INSURANCE PTE LTD

(Kenneth - LKK)

DATE : 10/05/2023

VEHICLE NO : SLB 2044 H

MAKE/MODEL : Mazda 3

ACC DATE : 15/01/2023

ESTIMATE

S/N	PC	List Items	Page . 1 .	AMOUNT S\$
1	1	Front bumper		Bu 1,038.00 ✓
2	2	Front bumper retainer @\$21.00		Sn 42.00 X
3	1	Front bumper reinforcement		R 485.00 X
4	1	Front bumper below grille		Sn 252.30 X
5	1	Front bumper centre grille		CM 445.00 —
6	1	Front bumper logo		nu 48.00 —
7	2	Front bumper below fog lamp @\$185.50		Sn 371.00 X
8	1	Front bonnet lid		R 1,221.00 X
9	2	Front headlamp @914.50		my car 1,829.00 ✓
10	1	Front LH fender		R 434.00 X
				6,165.30
Less 20%				(1,233.06)
				4,932.24
Special Items :				
1	2	Number plate with casing		Sn 50.00 —
2	1	Front bumper clip (1 set)		nu 50.00 —
3	1	Front bumper grille clip (1 set)		nu 30.00 —
4	2	Front headlamp clip (1 set)		nu 40.00 X
				510.00
Labour Charges				
1		To check up electrical wiring		180.00 201
2		To respray painting & etc		600.00 4001
3		Panel beat, remove and replacing above parts		800.00 4001
				1,580.00
Total Repair Cost				7,022.24

(S/DLS : Seventy Thousand twenty-two and cents Twenty-four only.)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 EMAIL :KIENCHEONG@YAHOO.COM.SG

The Motor Claims Dept.

LIBERTY INSURANCE PTE LTD

(KENNETH - LKK)

DATE : 11/5/2023

VEHICLE NO : SLB 2044 H

MAKE/MODEL : MAZDA 3

ACC DATE : 15/1/2023

ESTIMATE

S/N	PC	List Items	Page . 1 .	AMOUNT S\$
1		2 Front bumper grille chrome @\$164.00	<i>MS R</i>	\$ 328.00 ✓
2		2 Front bumper below corner cover @31.00	<i>MC</i>	\$ 62.00 ✓
3		1 Front support panel seal plate	<i>\$ DIT</i>	\$ 86.00 ✓
				\$ 476.00
				\$ (95.20)
				\$ 380.80

Less 20%

