

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0435/2023/EQ
DATE : 5-May-23
WIP : 19244

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/5/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnr

12-Jul-23

OWNER'S NAME : MR CHIA LEE HUAT EDWARD
ADDRESS : 24 SIMEI RISE
#05-65 CHANGI RISE
SINGAPORE 528811
TELEPHONE : HP +65 97351217
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220147639
VEHICLE NO : **SFL 6550 E**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 19/12/2022
ENGINE NO : DFY 308623
CHASSIS NO : WAUZZZGY3NA026619
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-May-23
PLACE OF ACCIDENT : ROCHOR RIVER BRIDGE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFL 6550 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	\$	3,000.00	\$	1,100.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00		
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,402.00	\$	2,772.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFL 6550 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,778.00	\$ 1,422.40
2	FRONT BUMPER FIXING PARTS	1	\$ 307.00	
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 137.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 281.00	
5	FRONT BUMPER AIR GUIDE - LH	1	\$ 71.00	
6	FRONT BUMPER TRIM COVER - LH	1	\$ 110.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 181.00	
8	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 46.00	
9	FRONT BUMPER GUIDE SECTION - LH	1	\$ 57.00	
10	FRONT PARKING AID SENSOR - LH	1	\$ 272.00	
11	FRONT PARKING AID SEAL RING	4	\$ 54.00	
12	FRONT FENDER - LH	1	\$ 1,313.00	\$ 1,050.40
13	FRONT FENDER RIVET	3	\$ 12.00	\$ 19.20
14	FRONT FENDER BRACE - LH	1	\$ 104.00	
15	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 34.00	
16	FRONT FENDER BRACKET - LH FRONT	1	\$ 49.00	
17	FRONT FENDER BRACKET - LH CENTER	1	\$ 38.00	
18	FRONT WHEEL HOUSING LINER - LH	1	\$ 198.00	
19	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH	1	\$ 24.00	
20	HEADLIGHT - LH	1	\$ 4,323.00	
SUB TOTAL SPARE PARTS		:	\$ 9,389.00	\$ 2,492.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFL 6550 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 2,492.00
21	LIFT CYLINDER - LH	1	\$ 223.00	
22	LIFT CYLINDER HOSE	1	\$ 112.00	
23	RUBBER VALVE	4	\$ 16.00	
24	LHS FRONT RIM	S/N	TBC	
25	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS			\$ 10,140.00	\$ 2,492.00
TOTAL LABOUR CHARGES			\$ 6,402.00	\$ 2,772.00
GRAND TOTAL			\$ 16,542.00	\$ 5,264.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.