

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0435/2023/EQ  
**DATE** : 5-May-23  
**WIP** : 19244

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/5/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR CHIA LEE HUAT EDWARD  
**ADDRESS** : 24 SIMEI RISE  
#05-65 CHANGI RISE  
SINGAPORE 528811  
**TELEPHONE** : HP +65 97351217  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220147639  
**VEHICLE NO** : **SFL 6550 E**  
**MODEL CODE** : AUDI A3 SEDAN 1.5 TFSI  
**MODEL YEAR** : 19/12/2022  
**ENGINE NO** : DFY 308623  
**CHASSIS NO** : WAUZZZGY3NA026619  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 4-May-23  
**PLACE OF ACCIDENT** : ROCHOR RIVER BRIDGE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### **ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFL 6550 E**

| S/N                         | NATURE OF JOBS                                                                                                                                    |        | ESTIMATED<br>CHARGES     | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ | 480.00                   | ✓                             |
| 2                           | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                             | S/N \$ | 350.00                   | X                             |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.    | \$     | <del>2,100.00</del> 1000 |                               |
| 4                           | TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.                                                                                             | \$     | <del>3,000.00</del> 1100 |                               |
| 5                           | TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                             | S/N \$ | 280.00                   | X                             |
| 6                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                    | S/N \$ | 192.00                   | ✓                             |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                   | :      | <b>\$ 6,402.00</b>       |                               |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFL 6550 E**

|                              |                                                               |          | DAMAGED PARTS & PRICES |         |  |
|------------------------------|---------------------------------------------------------------|----------|------------------------|---------|--|
| S/N                          | PARTS DESCRIPTION                                             | QTY      | S/NETT                 | REMARKS |  |
| 1                            | FRONT BUMPER <i>Rehnd</i>                                     | 1        | \$ 1,778.00            | —       |  |
| 2                            | FRONT BUMPER FIXING PARTS <i>3 x 2 m</i>                      | 1        | \$ 307.00              | +       |  |
| 3                            | FRONT BUMPER CLOSING ELEMENT - LH <i>3 x 2 m</i>              | 1        | \$ 137.00              | +       |  |
| 4                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>1 x 2 m</i>    | 1        | \$ 281.00              | +       |  |
| 5                            | FRONT BUMPER AIR GUIDE - LH <i>3 x 2 m</i>                    | 1        | \$ 71.00               | +       |  |
| 6                            | FRONT BUMPER TRIM COVER - LH <i>3 x 2 m</i>                   | 1        | \$ 110.00              | +       |  |
| 7                            | FRONT BUMPER AIR GUIDE GRILLE - LH <i>3 x 2 m</i>             | 1        | \$ 181.00              | +       |  |
| 8                            | FRONT PARKING AID SENSOR SUPPORT - LH <i>3 x 2 m</i>          | 1        | \$ 46.00               | +       |  |
| 9                            | FRONT BUMPER GUIDE SECTION - LH <i>3 x 2 m</i>                | 1        | \$ 57.00               | +       |  |
| 10                           | FRONT PARKING AID SENSOR - LH <i>3 x 2 m</i>                  | 1        | \$ 272.00              | +       |  |
| 11                           | FRONT PARKING AID SEAL RING <i>3 x 2 m</i>                    | 4        | \$ 54.00               | +       |  |
| 12                           | FRONT FENDER - LH <i>Dented</i>                               | 1        | \$ 1,313.00            | —       |  |
| 13                           | FRONT FENDER RIVET <i>3</i>                                   | 3        | \$ 12.00               | ?       |  |
| 14                           | FRONT FENDER BRACE - LH <i>3</i>                              | 1        | \$ 104.00              | ?       |  |
| 15                           | FRONT FENDER CLOSING ELEMENT - LH <i>3</i>                    | 1        | \$ 34.00               | ?       |  |
| 16                           | FRONT FENDER BRACKET - LH FRONT <i>3</i>                      | 1        | \$ 49.00               | ?       |  |
| 17                           | FRONT FENDER BRACKET - LH CENTER <i>3</i>                     | 1        | \$ 38.00               | ?       |  |
| 18                           | FRONT WHEEL HOUSING LINER - LH <i>3 x 2 m</i>                 | 1        | \$ 198.00              | +       |  |
| 19                           | FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH <i>3 x 2 m</i> | 1        | \$ 24.00               | +       |  |
| 20                           | HEADLIGHT - LH <i>3 x 2 m</i>                                 | 1        | \$ 4,323.00            | +       |  |
| <b>SUB TOTAL SPARE PARTS</b> |                                                               | <b>:</b> | <b>\$ 9,389.00</b>     |         |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFL 6550 E**

|                             |                    |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|--------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION  | QTY | S/NETT                 | REMARKS |
| 21                          | LIFT CYLINDER - LH | 1   | \$ 223.00              | +       |
| 22                          | LIFT CYLINDER HOSE | 1   | \$ 112.00              | +       |
| 23                          | RUBBER VALVE       | 4   | \$ 16.00               | +       |
| 24                          | LHS FRONT RIM      | S/N | TBC                    | +       |
| 25                          | SUNDRIES           |     | \$ 400.00              | ?       |
| <b>TOTAL SPARE PARTS</b>    |                    | :   | <b>\$ 10,140.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                    | :   | <b>\$ 6,402.00</b>     |         |
| <b>GRAND TOTAL</b>          |                    | :   | <b>\$ 16,542.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian Lim  
10/05/23

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: XAP Authorized, 04 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT