



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/III23000903/Wqy3-1

INDIA INTERNATIONAL INSURANCE PL  
64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Ref: ~~CS3/III23000903/y3~~  
Date: ~~30/01/2023~~ 10/05/2023  
Code: III2

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLM 2908H	Veh. Inspected	GBJ 1241M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	<del>JACELYN LOH</del> CARINE KEK	Assign Date	<del>30/01/2023</del> 10/05/2023

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--

### 5. General Information

Accident Date	26/01/2023	Inspection Date	
Survey held at	Motormed Pte Ltd 8 Kaki Bukit Avenue 4 Premier@Kaki Bukit	#02-14/44 Singapore 415875	

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.