

ASS. REC. BY:

REF:

EQ / 2300-4779/Kg

Henneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SHD 59378

Yr Regn:

11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Puv

C.G

1798

Colour

M.P. White / PW

AC:

Insured / Std / NI / NA

Sp. Reading

284704

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3F4003078959

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size:

Continental 195/65R15

R: Wanli

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

9/5/23

D.O.I.

11/5/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

P.M.S

Others

Add Fee:

: Site Insp (\$

: Interview (\$

Tech Invs (\$

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5937Z

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

11 MAY 2023

SHD5937Z

JTDKB3FU003076959

200303878K

TOYOTA

PRIUS

9/5/2023

GBA5011G/EQ

22/11/2018

PART

LIST

1	COVER, REAR BUMPER	\$	Ru	558.39	—
1	COVER, REAR BUMPER, LOWER	\$	Ru	19.43	—
1	GUARD, REAR BUMPER, CENTER	\$	Ru	726.92	—
1	SEAL, REAR BUMPER SIDE, LH	\$	Ru	111.41	X
1	SEAL, REAR BUMPER SIDE, RH	\$	Ru	111.41	X
1	FILLER, REAR BUMPER EXTENSION, RH	\$	Ru	155.72	X
1	FILLER, REAR BUMPER EXTENSION, LH	\$	Ru	155.72	X
1	RETAINER, REAR BUMPER SIDE, LH	\$	Ru	147.11	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	Ru	148.58	X
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	Ru	419.90	—
1	COVER, FLOOR UNDER, RH	\$		220.50	?
1	COVER, FLOOR UNDER, LH	\$		304.92	?
1	COVER, REAR FLOOR	\$		290.43	?
1	BOX, DECK FLOOR, REAR	\$	Ru	133.25	X
1	BOX, DECK FLOOR, RH	\$	Ru	395.12	X
1	BOX, DECK FLOOR, LH	\$	Ru	394.38	X
1	BOARD, REAR FLOOR, NO.1	\$	Ru	654.78	X
1	COVER, DECK TRIM, REAR	\$	Ru	159.39	X
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	\$	Ru	68.57	—
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	Ru	824.46	—
1	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$	Ru	570.15	X
1	LENS AND BODY, REAR LAMP, RH	\$	Ru	634.73	X
1	COVER, REAR COMBINATION LAMP, RH	\$	Ru	81.48	X
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	Ru	559.13	X
1	LENS AND BODY, REAR LAMP, LH	\$	Ru	634.73	X
1	COVER, REAR COMBINATION LAMP, LH	\$	Ru	81.48	X
1	PANEL SUB-ASSY, BACK DOOR	\$	Ru	1,443.86	X
1	SPOILER SUB-ASSY, REAR	\$	Ru	1,986.92	X
1	SEAL, REAR SPOILER	\$	Ru	21.32	X
1	STAY ASSY, BACK DOOR, LH	\$	Ru	305.66	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5937Z

- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 UNIT ASSY, HEADLAMP, RH
- 1 LAMP ASSY, FOG, LH
- 1 LAMP ASSY, FOG, RH
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 CAP SUB-ASSY, AIR CLEANER
- 1 CASE SUB-ASSY, AIR CLEANER

\$	Pr	305.66	X
\$	Pr	77.18	X
\$	Pr	77.18	X
\$	Pr	1,171.38	—
\$	Pr	68.88	—
\$	Pr	68.88	—
\$	Pr	90.30	—
\$	Pr	653.31	—
\$		100.17	?
\$		902.16	?
\$	Pr	100.49	—
\$	Pr	100.49	X
\$	Pr	59.85	X
\$	Pr	59.85	X
\$	Pr	37.07	X
\$	Pr	37.07	X
\$	Pr	3,325.56	—
\$	Pr	3,325.56	X
\$	Pr	1,200.78	X
\$	Pr	1,200.78	X
\$	Pr	214.41	—
\$	Pr	436.38	—
\$	Pr	114.98	—
\$	Pr	680.30	X
\$	Pr	288.02	X
TOTAL	\$	27,016.42	27016.54
25%	\$	6,754.11	6754.14
	\$	20,262.32	20262.41

SPECIAL NETT
1SET PARKING AID

- 1 REAR BUMPER CLIP
- 1 REAR SPOILER CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO.
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR BUMPER ADVERTISEMENT
- 1 FRT BUMPER CLIP
- 1 FRT NUMBER PLATE WITH MOULDING
- 1 END PANEL INNER TRIM CLIP

\$	Pr	700.00	2201N—
\$	Pr	65.00	601N
\$	Pr	65.00	*
\$	Pr	100.00	301N
\$	Pr	100.00	301N
\$	Pr	65.00	X
\$	Pr	65.00	X
\$	Pr	100.00	X
\$	Pr	65.00	601N
\$	Pr	180.00	451N
\$	Pr	60.00	—

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5937Z**AAD2305-**

1	REAR BUMPER PROTECTOR	\$	nn	180.00	X
2	WINDSCREEN SEALANT	\$	nn	150.00	X
1	WINDSCREEN MOULDING	\$	nn	200.00	X
1	WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	X
TOTAL		\$		2,225.00	
TOTAL PARTS		\$		22,487.32	

LABOUR

To rust-proofing of the affected areas.	\$	600.00	300
Putty and spray painting of the affected portion.	\$	1,200.00	800
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	800
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	600
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	170.00 X
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	500
To check steering geometry and computer wheel alignment	\$	nn	220.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel Nc Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHD5937Z

AAD2305-

TOTAL \$ 5,420.00

OVERALL TOTAL \$ 27,907.32 27907.41

7 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/05/2023 19:16 (SGT)
Reported by	Actual Driver
Date of Accident	09/05/2023 14:15 (SGT)
Exact Location of Accident	Near CQ8C+XF Singapore
Additional Location Information	BKE TOWARDS SLE BEFORE SLE EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD5937Z

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	(Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	PRIUS 5 DR HATCHBACK (AUTO)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798



INSURANCE COMPANY

Name of Insurance Company	HSBC Life (Singapore) Pte. Ltd
Policy Number / Cover Note Number	VFX/P2413997

DRIVER

Name of Driver	LEE HIAN GUAN
NRIC No	SXXXX409D
Date Of Birth	31/03/1961
Occupation	Outdoor

ACCIDENT



A. SHIDEA372

B. GORASO16

C. SK866A1K

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Wong Jun Keat

Witnessed by Reporting Centre
Personnel