

ASS. REC. BY:

REF:

EQ / 2300-4779/Kg43

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SID 59378

Yr Regn:

11.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Puv

C.C

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

284704

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU003078959

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / RIM or

Tyre Size:

Continental 195/65R15

R: Wanli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

5

mm

L/Bal.

8

mm

L/Bal.

5

mm

D.O.A.

9/5/23

D.O.I.

11/5/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

8 / 15

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/5 11:00pm @ 7750h Car had \$20877.17, 73%

Date/Time, File Pass to?

☐

: Prell. Report

1) 31/5 11:00pm

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

7

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

P. 100

Others

TOTAL

Report Format:

TP

Lump Sum / L.B.I. (\$

7750

Not Notarized
 1/1 Png &
 Recovery After Paint
 AAD2305-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5937Z

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

11 MAY 2023

SHD5937Z

JTDKB3FU003076959

200303878K

TOYOTA

PRIUS

9/5/2023

GBA5011G/EQ

22/11/2018

PART

LIST

1 COVER, REAR BUMPER	\$ <i>Re</i> <i>Re</i> 558.39	✓
1 COVER, REAR BUMPER, LOWER	\$ <i>Re</i> <i>Re</i> 19.43	✓
1 GUARD, REAR BUMPER, CENTER	\$ <i>Re</i> <i>Re</i> 726.92	✓
1 SEAL, REAR BUMPER SIDE, LH	\$ <i>Re</i> <i>Re</i> 111.41	X
1 SEAL, REAR BUMPER SIDE, RH	\$ <i>Re</i> <i>Re</i> 111.41	X
1 FILLER, REAR BUMPER EXTENSION, RH	\$ <i>Re</i> <i>Re</i> 155.72	X
1 FILLER, REAR BUMPER EXTENSION, LH	\$ <i>Re</i> <i>Re</i> 155.72	X
1 RETAINER, REAR BUMPER SIDE, LH	\$ <i>Re</i> <i>Re</i> 147.11	X
1 RETAINER, REAR BUMPER SIDE, RH	\$ <i>Re</i> <i>Re</i> 148.58	X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ <i>Re</i> <i>Re</i> 419.90	✓
1 COVER, FLOOR UNDER, RH	\$ <i>SVC</i> 220.50	? X
1 COVER, FLOOR UNDER, LH	\$ <i>SVC</i> 304.92	? X
1 COVER, REAR FLOOR	\$ <i>SVC</i> 290.43	? X
1 BOX, DECK FLOOR, REAR	\$ <i>Re</i> <i>Re</i> 133.25	X
1 BOX, DECK FLOOR, RH	\$ <i>Re</i> <i>Re</i> 395.12	X
1 BOX, DECK FLOOR, LH	\$ <i>Re</i> <i>Re</i> 394.38	X
1 BOARD, REAR FLOOR, NO.1	\$ <i>Re</i> <i>Re</i> 654.78	X
1 COVER, DECK TRIM, REAR	\$ <i>Re</i> <i>Re</i> 159.39	X
1 MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	\$ <i>Re</i> <i>Re</i> 68.57	✓
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ <i>Re</i> <i>Re</i> 824.46	✓
1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$ <i>Re</i> <i>Re</i> 570.15	X
1 LENS AND BODY, REAR LAMP, RH	\$ <i>Re</i> <i>Re</i> 634.73	X
1 COVER, REAR COMBINATION LAMP, RH	\$ <i>Re</i> <i>Re</i> 81.48	X
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$ <i>Re</i> <i>Re</i> 559.13	X
1 LENS AND BODY, REAR LAMP, LH	\$ <i>Re</i> <i>Re</i> 634.73	X
1 COVER, REAR COMBINATION LAMP, LH	\$ <i>Re</i> <i>Re</i> 81.48	X
1 PANEL SUB-ASSY, BACK DOOR	\$ <i>Re</i> <i>Re</i> 1,443.86	X
1 SPOILER SUB-ASSY, REAR	\$ <i>Re</i> <i>Re</i> 1,986.92	X
1 SEAL, REAR SPOILER	\$ <i>Re</i> <i>Re</i> 21.32	X
1 STAY ASSY, BACK DOOR, LH	\$ <i>Re</i> <i>Re</i> 305.66	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5937Z**AAD2305-**

- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 UNIT ASSY, HEADLAMP, RH
- 1 LAMP ASSY, FOG, LH
- 1 LAMP ASSY, FOG, RH
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 CAP SUB-ASSY, AIR CLEANER
- 1 CASE SUB-ASSY, AIR CLEANER

\$	<i>Sn</i>	305.66	X
\$	<i>R</i>	77.18	✓
\$	<i>R</i>	77.18	X
\$	<i>way pin</i>	1,171.38	—
\$	<i>me</i>	68.88	—
\$	<i>me</i>	68.88	—
\$	<i>me</i>	90.30	—
\$	<i>Bu</i>	653.31	—
\$	<i>SVC</i>	100.17	?X
\$	<i>SVC</i>	902.16	7X
\$	<i>Dir</i>	100.49	—
\$	<i>R</i>	100.49	X
\$	<i>R</i>	59.85	X
\$	<i>R</i>	59.85	X
\$	<i>R</i>	37.07	X
\$	<i>R</i>	37.07	X
\$	<i>mgom</i>	3,325.56	—
\$	<i>R</i>	3,325.56	X
\$	<i>R</i>	1,200.78	X
\$	<i>R</i>	1,200.78	X
\$	<i>Dir</i>	214.41	—
\$	<i>Dir</i>	436.38	—
\$	<i>me</i>	114.98	—
\$	<i>R</i>	680.30	X
\$	<i>R</i>	288.02	X
TOTAL		\$ 27,016.42	
25%		\$ 6,754.11	
		\$ 20,262.32	

SPECIAL NETT**1SET PARKING AID**

- 1 REAR BUMPER CLIP
- 1 REAR SPOILER CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO.
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR BUMPER ADVERTISEMENT
- 1 FRT BUMPER CLIP
- 1 FRT NUMBER PLATE WITH MOULDING
- 1 END PANEL INNER TRIM CLIP

\$	<i>nd</i>	700.00	220JA—
\$	<i>me</i>	65.00	60JA
\$	<i>An</i>	65.00	X
\$	<i>me</i>	100.00	30JA
\$	<i>na</i>	100.00	30JA
\$	<i>na</i>	65.00	X
\$	<i>na</i>	65.00	X
\$	<i>na</i>	100.00	X
\$	<i>na</i>	65.00	60JA ✓
\$	<i>B</i>	180.00	45JA
\$	<i>me</i>	60.00	—

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2305-**SHD5937Z**

1	REAR BUMPER PROTECTOR	\$	nn	180.00	X
2	WINDSCREEN SEALANT	\$	nn	150.00	X
1	WINDSCREEN MOULDING	\$	nn	200.00	X
1	WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	X
TOTAL		\$		2,225.00	
TOTAL PARTS		\$		22,487.32	

LABOUR

To rust-proofing of the affected areas.	\$	600.00	301
Putty and spray painting of the affected portion.	\$	1,200.00	8801
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	8001
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	170.00 X
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	501
To check steering geometry and computer wheel alignment	\$	nn	220.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5937Z

AAD2305-

TOTAL \$ 5,420.00

OVERALL TOTAL \$ 27,907.32

7 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel Nc Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHD5937Z

AAD2305-

Vehicle No.:	SHD5937Z
Chassis No.:	JTDKB3FU003076959
Co UEN.:	200303878K
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS
Date of Accident:	9/5/2023
Third Party Insurer:	GBA5011G/EQ
Date of Registration:	22/11/2018
SUPPLEMENTARY	

PART

LIST

- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 MOULDING SUB-ASSY, ROOF TOP

\$	<i>cm</i>	130.31	
\$	<i>cm</i>	829.50	
TOTAL \$		959.81	
25% \$		239.95	
\$		719.85	