

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\; F$

Immediate Advice

To: HSBC Life (Singapore) Pte. Ltd. Date: 26/05/2023

Survey Details:

Date of loss	8-May-23	
Date of appointment	10-May-23	
Date of survey	10-May-23	
Location of survey	LEE BROTHERS AUTOMOTIVE PTE	LTD

Vehicle Details:

Claim Type:	Third par	Third party	
Vehicle number	SMS5340	SMS5340G	
Make and Model	тоуота	HARRIER (1986cc)	
Date of registration	25/09/20)15	
Excess	NIL		
Market Value/ Book Value	\$	55,000.00	(est)
Parf/COE Rebate	\$	30,757.00	(est)
Nett Value/ ERV	\$	24,243.00	(est)

Repair details:

Initial Estimate \$	\$ 11,077.97
---------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,440.24
Check items (estimate)	-
Labour	\$ 1,710.00
Supplementary	-
Total	\$ 7,150.24
Lump Sum(if applicable)	\$ 5,700.00

Number of days for repair	Number of days for repair	4
---------------------------	---------------------------	---



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Remarks:

OID CAME OUT FROM SLIP ROAD.	

Mandate:

Liability(TP)	ТВА	
Proposed repair cost	\$ 6,156.00	(WITH GST)
Loss of use	NIL	
Loss of rental (4DAYS X \$100)	\$ 432.00	(WITH GST)
Loss of income	NIL	
LTA/GIA search fees	\$ 26.75	
Others	NIL	
Proposed Total	\$ 6,614.75	