



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: TEO KITTY		Ref: CS/HSB23004788/Kvp3e2 Date: 26/05/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SH 7318X	Veh. Inspected	SMQ 9879D
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04M98	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	10/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA NOAH (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800410836	Colour	METALLIC PEARL WHITE
Odometer	274300 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FARROAD	9 mm
L/H Front Tyre	195/65 R15	FARROAD	9 mm
R/H Rear Tyre	195/65 R15	FARROAD	9 mm
L/H Rear Tyre	195/65 R15	FARROAD	9 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	27/04/2023	Inspection Date	16/05/2023
Survey held at	BLK 5034, #01-337, ANG MO KIO INDUSTRIAL PARK 2, Si		
Repairer	LIAN HER MOTORS		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	