

SIN YU SIN WORKSHOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SLQ7533B 2017 JULY
VEHICLE MODEL : MERCEDES BENZ C200
CHASSIS NO : WDD2050422R282930

TP Allianz.
Xiao Tony

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT NUMBER PLATE GARNISH <i>Not Nec</i>	1	\$ 98.00	\$ 98.00
2	FRONT BUMPER <i>Behind</i>	1	\$ 1,674.00	\$ 1,674.00
3	FRONT BUMPER SIDE HOLDER <i>Dmd</i>	1	\$ 85.00	\$ 85.00
4	FRONT BUMPER SENSOR <i>1 piece dmd</i>	2	\$ 275.00	\$ 550.00
5	FRONT BUMPER SENSOR HOLDER <i>new</i>	4	\$ 25.00	\$ 100.00
6	FRONT BUMPER SIDE GRILLE <i>crushd.</i>	1	\$ 82.00	\$ 82.00
7	FRONT BUMPER SPONGE <i>crushd.</i>	1	\$ 155.00	\$ 155.00
8	FRONT BUMPER REINFORCEMENT <i>Best.</i>	1	\$ 645.00	\$ 645.00
9	FRONT BUMPER REINFORCEMENT STAY <i>Best</i>	1	\$ 277.00	\$ 277.00
10	FRONT BUMPER TOP BEAM <i>Dmd</i>	1	\$ 224.00	\$ 224.00
11	FRONT BUMPER INNER SIDE BRACKET <i>Dmd</i>	1	\$ 104.00	\$ 104.00
12	FRONT BUMPER UNDERCOVER <i>Not Nec</i>	1	\$ 345.00	\$ 345.00
13	FRONT BUMPER INNER FRAME <i>Dmd.</i>	1	\$ 199.00	\$ 199.00
14	FRONT BUMPER LOWER CHROME CENTRE <i>Not Nec</i>	1	\$ 360.00	\$ 360.00
15	FRONT BUMPER LOWER CHROME SIDE <i>crushd.</i>	1	\$ 148.00	\$ 148.00
16	FRONT BUMPER LOWER GRILLE <i>Not Nec</i>	1	\$ 182.00	\$ 182.00
17	FRONT GRILLE <i>crushd</i>	1	\$ 1,419.00	\$ 1,419.00
18	FRONT GRILLE LOGO <i>new</i>	1	\$ 128.00	\$ 128.00
19	HEADLAMP <i>crushd.</i>	1	\$ 3,617.00	\$ 3,617.00
20	HEADLAMP LOWER BRACKET <i>crushd</i>	1	\$ 115.00	\$ 115.00
21	HEADLAMP ECU <i>Not Nec</i>	1	\$ 645.00	\$ 645.00
22	HEADLAMP PANEL <i>Not Nec</i>	1	\$ 218.00	\$ 218.00
23	FRONT FENDER <i>crushd</i>	1	\$ 971.00	\$ 971.00
24	FRONT FENDER INNER SHIELD <i>Not Nec</i>	1	\$ 149.00	\$ 149.00
25	FRONT SUPPORT PANEL <i>Not Nec</i>	1	\$ 758.00	\$ 758.00
26	BONNET <i>Dented</i>	1	\$ 2,277.00	\$ 2,277.00
27	BONNET LOCK <i>Not Nec</i>	1	\$ 188.00	\$ 188.00
28	BONNET LOCK BRACKET <i>Best.</i>	1	\$ 329.00	\$ 329.00
29	BONNET LOGO <i>new</i>	1	\$ 85.00	\$ 85.00
30	FRONT WHEEL RIM <i>Not Nec</i>	1	\$ 1,280.00	\$ 1,280.00

12909

1161810

TOTAL PRICE: \$ 17,407.00
LESS 10% \$ 1,740.70
SUB TOTAL PRICE: \$ 15,666.30

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT NUMBER PLATE <i>3 NLP</i>	1	\$ 30.00	\$ 30.00
2	FRONT BUMPER PLATE HOLDER <i>1 New</i>	1	\$ 30.00	\$ 30.00

3	FRONT BUMPER CLIPS <i>New</i>	1 SET	\$ 50.00	\$ 50.00	✓
4	FRONT BUMPER UNDERCOVER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00	✓
5	FRONT GRILLE CLIPS <i>me</i>	1 SET	\$ 20.00	\$ 20.00	✓
6	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
7	COOLANT <i>for</i>	1	\$ 50.00	\$ 50.00	✓
8	FRONT TYRE <i>for</i>	1	\$ 300.00	\$ 300.00	✓
			TOTAL :	\$ 540.00	

70

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	<i>8w</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>750</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>40</i>	
5	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	\$ 120.00	<i>x</i>	
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	<i>x</i>	
7	TO PERFORM DIAGNOSTIC TEST	\$ 200.00	<i>150</i>	
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>x</i>	
		TOTAL: \$ 3,240.00	<i>1770</i>	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 16,206.30

TOTAL LABOUR COST: \$ 3,240.00

TOTAL REPAIR COST: \$ 19,446.30

total: 13458.10

L/s: 10750

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: