

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	23/ALL/OD-257(05)
Policy No:	SP2001919392-01	Date of Loss:	08/05/2023
Vehicle Reg. No.:	SMM7407S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOW ZHEN YANG		
Driver:	LOW ZHEN YANG		

Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	12/07/2019
Vehicle Colour:	SILVER		
Engine No:	G4FGKU134763	Chassis No:	KMHD841CMKU902441
Odometer:	0 KM		

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair
 (day) **10-5**

Remarks: VEHICLE IN, KINDLY ARRANGE FOR SURVEY.
 Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS	Amount
Parts	6,233.70
Miscellaneous Items	65.00
Labour	1,730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,028.70
+ GST 8.00% (S\$)	642.30
Nett Amount (S\$)	8,671.00

This claim is handled by: WEN YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 May 2023)
Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: SME Motor Pte Ltd/SMM7407S/09/05/2023 16:11
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRT BONNET	0.00	0.00	*780.00F	B/C
2	2		*FRT BONNET HINGES	0.00	0.00	*110.00F	?
3	1		*FRT BONNET LOCK	0.00	0.00	*95.00F	?
4	1		*FRT GRILLE	0.00	0.00	*580.00F	CRA
5	1		*GRILLE CENTRE LOGO	0.00	0.00	-	NEC
6	4		*GRILLE CLIPS	0.00	0.00	*8.00F	NEC
7	1		*FRT BUMPER	0.00	0.00	*330.00F	BR
8	2		*FRT BUMPER RETAINER RH-BT, LH-NN	0.00	0.00	*40.00F	X
9	10		*FRT BUMPER CLIPS	0.00	0.00	*20.00F	NEC
10	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*105.00F	CRA
11	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*380.00F	?
12	2		*HEADLAMP	0.00	0.00	*1,720.00F	?
13	1		*HEADLAMP SUPPORT PANEL	0.00	0.00	*350.00F	?
14	1		*HEADLAMP SUPPORT TOP GARNISH	0.00	0.00	*85.00F	XNN
15	8		*TOP GARNISH CLIPS	0.00	0.00	*16.00F	NEC
16	1		*AIRCON CONDENSER	0.00	0.00	*250.00F	XNN
17	1		*RADIATOR	0.00	0.00	*280.00F	XNN
18	1		*RH HEADLAMP BRACKET	0.00	0.00	*28.00F	?
19	1		*RH AIRCON SIDE DEFLECTOR	0.00	0.00	*40.00F	?
20	1		*FRT RH FENDER	0.00	0.00	*450.00F	BT
21	1		*NUMBER PLATE GARNISH	0.00	0.00	-	CRA

F=Franchise part.

Sub Total (\$\$)	5,667.00
+ Margin on L,N Items 10.00% (\$\$)	566.70
Total Parts (\$\$)	6,233.70

SME Motor Pte Ltd/SMM7407S/09/05/2023 16:11. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	NUMBER PLATE	40.00
2	1	RADIATOR COOLANT	25.00
Sub Total (S\$)			65.00

CRA
?

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00
3	LABOUR CHARGE	New	700.00
4	SPRAY PAINTING	New	900.00
Gross Labour Cost (S\$)			1,730.00

500
700

SME Motor Pte Ltd/SMM7407S/09/05/2023 16:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise -
- Excess \$600/=
- Survey by Simon Ho (62563561)
- Resurvey before paint for P/P repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: