

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 11 May 2023

Preliminary Advice

Vehicle No	: SMM7407S	Accident Date	: 08/05/2023
Make	: HYUNDAI AVANTE	Policy No.	: SP2001919392-01
Assignment Date	: 10/05/2023	Excess	: S\$600.00
Date of Inspection	: 11/05/2023	Est. Duration of Repair	: 5
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,028.70
Revised Amount	:S\$	3,809.90
Check Items (Estimated)	:S\$	3,120.30
Total	:S\$	6,930.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	27,550.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,450.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :the vehicle repair on part by parts basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.