

SMM 7407S

5/11/23, 10:52 AM

Repairer Estimates

REPAIR DETAILS	
<b>Reference</b>	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: SME Motor Pte Ltd/SMM7407S/09/05/2023 16:11	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRT BONNET	0.00	0.00	*780.00F	B/C
2	2		*FRT BONNET HINGES	0.00	0.00	*110.00F	CBT
3	1		*FRT BONNET LOCK	0.00	0.00	*95.00F	XNN
4	1		*FRT GRILLE	0.00	0.00	*580.00F	CRA
5	1		*GRILLE CENTRE LOGO	0.00	0.00	-	NEC
6	4		*GRILLE CLIPS	0.00	0.00	*8.00F	NEC
7	1		*FRT BUMPER	0.00	0.00	*330.00F	BR
8	2		*FRT BUMPER RETAINER RH-BT, LH-NN	0.00	0.00	*40.00F	X
9	10		*FRT BUMPER CLIPS	0.00	0.00	*20.00F	NEC
10	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*105.00F	CRA
11	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*380.00F	DD
12	2		*HEADLAMP	0.00	0.00	*1,720.00F	SRA
13	1		*HEADLAMP SUPPORT PANEL	0.00	0.00	*350.00F	CRA
14	1		*HEADLAMP SUPPORT TOP GARNISH	0.00	0.00	*85.00F	XNN
15	8		*TOP GARNISH CLIPS	0.00	0.00	*16.00F	NEC
16	1		*AIRCON CONDENSER	0.00	0.00	*250.00F	XNN
17	1		*RADIATOR	0.00	0.00	*280.00F	XNN
18	1		*RH HEADLAMP BRACKET	0.00	0.00	*28.00F	CUT
19	1		*RH AIRCON SIDE DEFLECTOR	0.00	0.00	*40.00F	BT
20	1		*FRT RH FENDER	0.00	0.00	*450.00F	BT
21	1		*NUMBER PLATE GARNISH	0.00	0.00	\$30-	CRA
			NO STOCK				

F=Franchise part.

Sub Total (\$)	5,667.00
+ Margin on L,N Items 10.00% (\$)	566.70
<b>Total Parts (\$)</b>	<b>6,233.70</b>

SME Motor Pte Ltd/SMM7407S/09/05/2023 16:11. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

grille new bracket for \$12 ✓ DIS  
Wash etc. \$65 ✓ CUT

