



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

not allowed
11/5/23
2/s # 5300
6 days

QUOTATION

No : QT-000372

HSBC LIFE (SINGAPORE) PTE. LTD.
 38 BEACH ROAD
 #03-11 SOUTH BEACH TOWER
 SINGAPORE 189767
 Attn: Motor Claim Department
 TEL : 62256111 FAX :

Your Ref. : SHC655A
 Vehicle No. : SLJ630L
 Make & Model : TOYOTA SIENTA
 Chasis No. : NSP1707050892
 Engine No. : 2NR8665444
 Accident Date : 09/05/2023
 Policy No. : 5086495039-05
 Date : 11/05/2023
 Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	REAR BOOT <i>body in</i>	1	PCS 1,229.85	1,229.85
2	LOGO <i>new</i>	1	PCS 53.82	53.82
3	WINDSCREEN MOULDING (REAR) <i>new</i>	1	PCS 72.24	72.24
4	REAR BOOT INNER TRIM BOARD <i>11</i>	1	PCS 145.40	145.40
5	REAR BOOT INNER TRIM BOARD CLIPS <i>11</i>	13	PCS 5.00	65.00
6	REAR BOOT GARNISH <i>11</i>	1	PCS 227.66	227.66
7	REAR BOOT ADJUSTER RUBBER <i>11</i>	2	PCS 18.88	37.76
8	REAR BOOT STOPPER BUSH <i>11</i>	2	PCS 15.51	31.02
9	REAR BOOT INNER LOCK <i>Daye</i>	1	PCS 395.97	395.97
10	REAR BOOT LOCK STRIKER <i>11</i>	1	PCS 32.78	32.78
11	REAR BOOT WEATHERSTRIP <i>new</i>	1	PCS 399.32	399.32
12	HANDLE (REAR BOOT) <i>11</i>	1	PCS 45.61	45.61
13	LAMP (REAR) (BOOT) (R/H) <i>11</i>	1	PCS 328.74	328.74
14	LAMP (R/H/R) <i>11</i>	1	PCS 462.02	462.02
15	TAIL LAMP BASE PANEL (R/H) <i>DD/Bent</i>	1	PCS 295.60	295.60
16	FENDER (R/H/R) <i>new</i>	1	PCS 1,594.39	1,594.39
17	FENDER QUARTER GLASS (REAR) (R/H) WITH MOULDING <i>11</i>	1	PCS 312.06	312.06
18	FENDER INNER TRIM (REAR) (R/H) <i>new</i>	1	PCS 806.10	806.10
19	COVER (FENDER INNER TRIM) <i>lower new</i>	1	PCS 167.40	167.40
20	CLIP (FENDER INNER TRIM) <i>new</i>	12	PCS 5.00	60.00
21	FENDER AIR GRILLE <i>11</i>	1	PCS 89.27	89.27
22	REAR BUMPER <i>Dis/trim</i>	1	PCS 396.00	396.00
23	BUMPER CLIP <i>new</i>	6	PCS 6.00	36.00
24	REAR BUMPER SPONGE <i>new</i>	1	PCS 91.48	91.48
25	PROTECTOR BUMPER (SIDE) (R/H) <i>Dis</i>	1	PCS 144.00	144.00
26	PROTECTOR BUMPER (CENTER) <i>Dis</i>	1	PCS 205.00	205.00
27	REAR BUMPER REFLECTOR (R/H) <i>one</i>	1	PCS 63.00	63.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

QUOTATION

No : QT-000372

HSBC LIFE (SINGAPORE) PTE. LTD.

38 BEACH ROAD
 #03-11 SOUTH BEACH TOWER
 SINGAPORE 189767
 Attn: Motor Claim Department

TEL : 62256111 FAX :

Your Ref. : SHC655A
 Vehicle No. : SLJ630L
 Make & Model : TOYOTA SIENTA
 Chasis No. : NSP1707050892
 Engine No. : 2NR8665444
 Accident Date : 09/05/2023
 Policy No. : 5086495039-05
 Date : 11/05/2023
 Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
28	BUMPER SIDE RETAINER (R/H/R) <i>cm</i>	1	88.00	88.00
29	LAMP BRACKET (R/H/R) <i>17</i>	1	95.00	95.00
30	REAR END PANEL (INNER) <i>R</i>	1	680.00	680.00
31	REAR END PANEL (OUTER) <i>3 of 5.00</i>	1	418.00	418.00
32	REAR END PANEL GARNISH <i>D.S</i>	1	192.21	192.21
33	SENSOR (REAR BOOT) <i>17</i>	1	295.45	295.45
34	SPARE TYRE BOARD <i>knj 7w1</i>	1	469.03	469.03
35	Discount 25 %			-2,506.30
36	SubTotal (L)			7,518.88
37	REAR END PANEL SEALANT <i>1m</i>	1	50.00	50.00
38	SEALANT (WINDSCREEN) <i>1m</i>	2	50.00	100.00
39	REVERSE SENSOR <i>no part</i>	1	280.00	280.00
40	SubTotal (S)			430.00
41	PANEL BEAT & REPAIR REAR DAMAGE	1	900	1,500.00
42	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1	1200	1,200.00
43	TO PROVIDE UNDER TURFCODE	1	80	120.00
44	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1	20	50.00
45	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1		80.00
46	TO REMOVE AND REFIT SIDE WINDSCREEN GLASS	1	150	150.00
47	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	120	150.00
48	TO REMOVE REVERSE SENSOR/CAMERA	1	50	150.00
49	TO TRANSFER REAR BOOT FITTING	1	60	120.00
50	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1	80	150.00
51	SubTotal (LABOUR)			3,670.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

QUOTATION

No : QT-000372

HSBC LIFE (SINGAPORE) PTE. LTD.

38 BEACH ROAD
 #03-11 SOUTH BEACH TOWER
 SINGAPORE 189767
 Attn: Motor Claim Department

TEL : 62256111

FAX :

Your Ref. : SHC655A
 Vehicle No. : SLJ630L
 Make & Model : TOYOTA SIENTA
 Chasis No. : NSP1707050892
 Engine No. : 2NR8665444
 Accident Date : 09/05/2023
 Policy No. : 5086495039-05
 Date : 11/05/2023
 Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
------	-------------	-----	-----------------	---------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5491.54
 252
 418.65
 290
 2310
 6718.65

SINGAPORE DOLLAR ELEVEN THOUSAND SIX HUNDRED EIGHTEEN AND CENTS EIGHTY EIGHT ONLY

E. & O.E

ZERO GRAVITY

Total	S\$	11,618.88
Discount	S\$	0.00
Net Total	S\$	11,618.88

Terms: C.O.D.

Customer's Signature/Co. Stamp

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise if is assumed that this bill is accepted as correct.