



V-TECH AUTO SERVICE

No.1 Soon Lee St #06-04/05/06/07 Pioneer Centre Singapore 627605

Tel: 62646211, 62646222 Fax: 62646233 Email: vtech.autoservice@gmail.com

Reg. S2949633W, GST Reg No. M90364098A

24 HRS TOWING SERVICES

Website: <http://vtechauto.com.sg>

Vehicle No. SNB 929 U

DESCRIPTION OF PART

	Qty	Cost
1 FRONT BONNET <i>W</i>	1	3,846.40
2 FRONT BONNET 'LOGO' EMBLEM <i>ms</i>	1	85.80
3 FRONT BONNET MECHANISM LOCK <i>?</i>	2	308.00
4 FRONT BONNET RUBBER GUIDE STOPPER L/R <i>ms</i>	2	32.00
5 FRONT BONNET DAMPER L/R <i>ms</i>	2	160.00
6 FRONT BONNET LOCK CATCH <i>?</i>	2	352.00
7 FRONT BONNET LOCK HANDLE <i>sea</i>	1	64.00
8 FRONT GRILLE <i>cm</i>	1	448.00
9 FRONT GRILLE TOP COVER <i>ad</i>	1	192.00
10 FRONT GRILLE CLIPS <i>ms</i>	6	32.00
11 FRONT LH HEADLAMP <i>bm</i>	1	3,051.40
12 FRONT LH HEADLAMP BULB 'ORIGINAL' <i>X</i>	1	
13 FRONT LH HEADLAMP L.E.D LAMP MODULE <i>?</i>	1	396.80
14 FRONT LH HEADLAMP LOWER BRACKET <i>?</i>	1	144.00
15 FRONT BUMPER <i>de</i>	1	2,908.80
16 FRONT BUMPER SIDE RETAINER L/R <i>X</i>	2	64.00
17 FRONT BUMPER INNER SPONGE <i>cm</i>	2	288.00
18 FRONT BUMPER REINFORCEMENT <i>?</i>	1	1,430.40
19 FRONT BUMPER FOGLAMP L/R <i>sea - LH/RH - X</i>	2	1,318.40
20 FRONT BUMPER FOGLAMP COVER L/R <i>RH - sea / LH - sea</i>	2	224.00
21 FRONT BUMPER FOGLAMP SIDE GARNISH L/R <i>RH - X / LH - ?</i>	2	192.00
22 FRONT BUMPER TOW HOOK COVER <i>X</i>	1	80.00
23 FRONT BUMPER BEAM <i>?</i>	1	320.00
24 FRONT BUMPER LOWER CENTER GRILLE <i>X</i>	1	176.00
25 FRONT BUMPER LOWER UNDER COVER <i>X</i>	1	208.80
26 FRONT BUMPER LH LOWER LID <i>X</i>	1	1,027.20

1	FRONT RH FENDER <i>bt/ ?</i>	1	1,484.80
28	FRONT RH FENDER BRACKET <i>?</i>	1	128.00
29	FRONT RH FENDER INNER SHIELD <i>X</i>	1	387.20
30	FRONT TOP AIR DUCT <i>?</i>	1	144.00
31	FRONT SUPPORT PANEL GARNISH <i>?</i>	1	112.00
32	FRONT SUPPORT PANEL <i>cm/</i>	1	1,587.20
33	AIRCON CONDENSER <i>?</i>	1	1,004.80
34	RADIATOR <i>?</i>	1	2,688.00
35			

Percentage discount 0%

	\$	24,886.00
	\$	-
Sub-total	\$	24,886.00

SPECIAL NETT ITEMS

1	FRONT LH SIGNAL BULB <i>X</i>	1	15.00 <i>X</i>
2	FRONT BUMPER CLIPS - SET <i>✓</i>	1	30.00 <i>✓</i>
3	FRONT BUMPER LH FOGLAMP BULB <i>X</i>	1	40.00 <i>X</i>
4	FRONT BUMPER LOWER UNDER COVER CLIPS - SET <i>X</i>	1	30.00 <i>X</i>
5	FRONT RH FENDER INNER SHIELD CLIPS - SET <i>✓</i>	1	30.00 <i>✓</i>
6	RADIATOR COOLANT - BOT <i>?</i>	1	80.00 <i>?</i>
7			
8			

Sub-total	\$	225.00
------------------	-----------	---------------

LABOUR

- 1 To provide towing charge. *receipt?* 50.00 ?
- 2 To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. ~~260~~ 140.00
- 3 To remove, reinstall air con parts, vacuums, refill air con gas. *?* ~~120?~~ 180.00
- 4 To reset system after repair works. ~~200~~ 400.00
- 5 To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. ~~900~~ 1,400.00
- 6 To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. ~~900~~ 1,800.00
- 7 To apply anti-rust chemical on repaired and replaced panel. ~~60~~ 120.00

Labour Total \$ 4,090.00

Parts & Labour Total \$ 29,201.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rand
Hy 900 loss
7 days
P/P
11/05/23 @ 121430
EXCESS: TBA
Revert
Resy before paint