

TP 87
AIG

SMRT Accident Vehicle Repair Estimates

SMKI Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/05/2023
User ID : munsan

Section A - Accident Details

Registration Number	SHB1783L
Case Reference Number	TAX/05/23/2029
Registration Date	5/2/16
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	FOO KOK WEE
Type of Accident	Side Swipe
Accident Date and Time	10/5/23 11:50 AM
Accident Reported Date and Time	10/5/23 1:39 PM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118392
Special Instruction to ARC, if any	TP/1 FET FRONT
Prepared Date and Time	10/5/23 2:27 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$976.00	\$0.00
Total Spare Part Cost	\$4,379.08	\$0.00
Total Other Cost	\$620.00	\$0.00
TOTAL COST	\$6,820.08	\$0.00
ump Sum Total	\$6,800.00	\$0.00
Number of Repair Days	7.0	3
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	10/05/2023 2:40 PM	
Signature		☒
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Tanjin 97495749
wp' 11/5/23 03pm
c/s Repair after repair
Tanjin C/Hantawu
3 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Pans prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

SMRT Accident Vehicle Repair Estimates

 SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63655592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

Date Generated : 10/05/2023

User ID : munsan

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR FRONT LH PORTION	\$845.00	300
Total Labour	\$845.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT BUMPER	\$378.00	200
O RESPRAY FRONT FENDER LH	\$378.00	200
O RESPRAY RIM	\$220.00	100
Total Spray Painting & Panel Beating	\$976.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00	X
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00	X
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	X
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	80
O REMOVE AND REFIT TYRE	\$120.00	X
O REPLACE SUNDRY PARTS	\$100.00	X
Total Other Costs	\$620.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$602.60	25.00	\$451.95	Replace	m
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	nel
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$86.20	25.00	\$64.65	Replace	de
		52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$21.40	25.00	\$16.05	Replace	X
		81210-12230	FOG LAMP RH	1.00	\$335.60	10.00	\$302.04	Replace	X
		81521-47050	LENS & BODY, FR TURN LH	1.00	\$581.40	10.00	\$523.26	Replace	X
		51444-12050	UNDER COVER SIDE/LH	1.00	\$52.50	25.00	\$39.38	Replace	X
		81170-47500	HEAD LAMP LH	1.00	\$1,075.40	10.00	\$967.86	Replace	X
		53802-47050	FENDER FRT/LH	1.00	\$916.30	25.00	\$687.22	Replace	Ry
		75374-47051	NAME PLATE (HYBRID)	1.00	\$59.20	25.00	\$44.40	Replace	nel
		53876-47030	FENDER LINER FRT/LH	1.00	\$195.40	25.00	\$146.55	Replace	m
		53852-47020	FENDER LINER PAD, FR WHEEL LH	1.00	\$56.30	25.00	\$42.22	Replace	?
		42611-47140	WHEEL DISC. FRONT	1.00	\$1,978.60	25.00	\$1,483.95	Replace	Ry
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	X
		43550-47011	WHEEL HUB FRT	1.00	\$722.10	25.00	\$541.58	Replace	X
Total					\$6,814.54		\$5,473.85		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									