



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/CTI22007208/Kqp3-1

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Ref: ~~CS3/CTI22007208/Kqp3~~Date: ~~20/07/2022~~ 10/05/2023

Code: CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	PA 8827J	Veh. Inspected	SLC 3405M
Policy No.		Coverage (\$)	0.00
Claim No.	SNM22D205267/C02/PA8827J/ THAMYL	Excess (\$)	0.00
Assign From	LYNN KIONG KAUSALYAH (JUST LAW LLC)	Assign Date	20/07/2022 10/05/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/07/2022	Inspection Date	29/07/2022
Survey held at	SERVE YOU MOTOR SERVICE BLK 5033 ANG MO KIO IND PK 2 #01-265 SINGAPORE 569536		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.