


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 09.05.2023

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBK4868E**
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 08.05.2023
TIME OF ACCIDENT : 17:00 HOURS

Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,370.00	\$ 1,370.00
2	TAILGATE HINGE <i>2 pieces danged</i>	4	\$ 165.00	\$ 660.00
3	TAILGATE SIDE LOCK <i>Not in</i>	2	\$ 125.00	\$ 250.00
4	TAILGATE STOPPER RUBBER <i>Not in</i>	2	\$ 35.00	\$ 70.00
5	TAILGATE STOPPER BRACKET RH <i>Not in</i>	1	\$ 175.00	\$ 175.00
6	SIDE GATE SAFETY LOCK <i>in</i>	2	\$ 132.10	\$ 264.20
7	TAIL LAMP <i>RH cracked</i>	2	\$ 245.00	\$ 490.00
8	TAIL LAMP SUPPORT BRACKET <i>RH Best</i>	2	\$ 185.00	\$ 370.00
9	REAR STICKER 'DYNA' <i>in</i>	1	\$ 45.00	\$ 45.00
10	REAR END PENEL <i>Dented</i>	1	\$ 1,245.00	\$ 1,245.00
11	REAR NUMBER PLATE PANEL <i>Best</i>	1	\$ 298.00	\$ 298.00
12	REAR SPARE TYRE CHAIN BOX <i>Best</i>	1	\$ 487.00	\$ 487.00
13	REAR CHASSIS CROSS MEMBER <i>Not in</i>	1	\$ 1,684.80	\$ 1,684.80

3203
2402.25

TOTAL PRICE \$ 7,409.00
LESS 25% \$ 1,852.25
SUB TOTAL PRICE \$ 5,556.75

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE ALUMINIUM COVER (SPECIAL TYPE) <i>Best</i>	1	\$ 680.00	\$ 680.00
3	TAIL GATE '70KM/H' STICKER <i>in</i>	1	\$ 40.00	\$ 40.00
4	TAIL GATE COMPANY STICKER (SPECIAL TYPE) <i>in</i>	2	\$ 380.00	\$ 760.00
5	TAILGATE STICKER '6 PAX' <i>in</i>	1	\$ 30.00	\$ 30.00
6	SIDE GATE STICKER 'QR' <i>Not in</i>	1	\$ 50.00	\$ 50.00
7	REAR END PENEL SEALANT <i>in</i>	1	\$ 150.00	\$ 150.00

✓
370
x
x
+
+
245.
185
-
495
155
298.
+

30
280
15
250
15
20
40

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBK4868E**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 08.05.2023
 TIME OF ACCIDENT : 17:00 HOURS

8	REAR FLOOR TOP ALUMINIUM PANEL (SPECIAL TYPE)	1	\$ 3,800.00	\$ 3,800.00	x
9	REAR SPARE TYRE BIG <i>Men</i>	1	\$ 300.00	\$ 300.00	x
10	REVERSE SENSOR (SET) <i>Dyna</i>	1	\$ 220.00	\$ 220.00	zw

830

TOTAL \$ 6,080.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,800.00	600
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,200.00	500
3	REMOVE AND REFIX REAR RAILING	\$ 350.00	x
4	REMOVE AND REFIX REVERSE SENSOR	\$ 80.00	50
5	REMOVE AND REFIX REAR FLOOR ALUMINIUM	\$ 650.00	x
6	REMOVE AND REFIX TAILGATE AND ALUMINIUM	\$ 250.00	x
7	REMOVE AND REFIX CANOPY	\$ 380.00	x
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,890.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,636.75
 TOTAL LABOUR COST : \$ 4,890.00
 TOTAL REPAIR COST : \$ 16,526.75

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
 W/S #1/05/23.

05 Days.

total: 4382.25

W/S: 3.5K ✓

1150