



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNJ 3330J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER ASSY	TO REPAIR SEE LABOUR	1,500.00	-
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	100.00	-
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	100.00	-
1	FRONT BUMPER RETAINERS LH	* CHECK	180.00	-
1	FRONT BUMPER GRILLE ASSY	NOT NECESSARY	1,200.00	-
1	FRONT VALANCE PANEL LOWER	NOT NECESSARY	300.00	-
1	FRONT BUMPER TRIM LH	CUT	350.00	350.00
1	FRONT FENDER LH	BENT	1,400.00	1,400.00
1	FRONT HEADLAMP LH	CUT	1,800.00	1,800.00
1	FRONT FENDER GARNISH LH	NOT NECESSARY	120.00	-
1	FRONT WHEEL HUB BEARING LH	NOT NECESSARY	400.00	-
1	FRONT WHEEL SHOCK ABSORBER LH	NOT NECESSARY	520.00	-
1	FRONT FOG LAMP TRIM LH	NOT NECESSARY	320.00	-
	LESS 10% DISCOUNT		-	-355.00
			8,290.00	3,195.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	250.00	30.00
1	SET FRONT BUMPER SENSORS (SN)	NOT NECESSARY	600.00	-
1	FRONT WHEEL TYRE LH (SN)	NOT NECESSARY	250.00	-
1	FRONT WHEEL SPORTS RIM LH (SN)	NOT NECESSARY	800.00	-
			1,900.00	30.00
	<b><u>LABOUR</u></b>			
	TO CUT, WELD, STRAIGHTEN AFFECTED AREAS AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER ASSY.		1,200.00	300.00
	TO PUTTY AND SPRAY PAINTING THE AFFECTED AREAS.		1,200.00	500.00
	TO CHECK FRONT LIGHTING AND WIRING.		120.00	30.00
	TO APPLY ANTI RUST PROOFING TO THE AFFECTED AREAS.		250.00	30.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL FRONT INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.	NOT NECESSARY	200.00	-
	TO CONDUCT VEHICLE FULL DIAGNOSIS AND FAULT FINDINGS TO FACILITATE THE REPAIR.	NOT NECESSARY	400.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	250.00	-
			3,620.00	860.00
<b>GRAND TOTAL</b>			<b>13,810.00</b>	<b>4,085.00</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$162.00 NETT)</b>				<b>4,085.00</b>

Report Ref No. CS/AGI23004833/Tvy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.