

ASS. REC. BY: TaughREF: CS/AG/123004833/Try

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 127K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNJ3330J Yr Regn: 2019, 206.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ilva Suenfo C.C. 2199.Colour: 8/ner A/C: Insured / Std / NI / NASp. Reading: 54935 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNV7P4815VAL5599971Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/50R19R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HZENIS

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 24/5/23Survey held at A-Tree

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

S + RS. SI

Photos

Others

Rep. Format: _____

A-Tec Automotive Pte Ltd

KIA SORENTO (SNJ3330J)

ESTIMATE VEHICLE COST OF REPAIR

List Items

No.	Description (Parts)	Cost of Repair
1	Front Bumper Assy	\$1,500.00 <i>Ry</i>
2	Front Bumper Bracket LH	\$100.00 <i>X</i>
3	Front Bumper Bracket RH	\$100.00 <i>X</i>
4	Front Bumper Retainers LH	\$180.00 <i>?</i>
4	Front Bumper Grille Assy	\$1,200.00 <i>X</i>
4	Front Valance Panel Lower	\$300.00 <i>X</i>
5	Front Bumper Trim LH	\$350.00 <i>cal</i>
6	Front Fender LH	\$1,400.00 <i>bt</i>
7	Front headlamp LH	\$1,800.00 <i>int</i>
8	Front Fender Garnish LH	\$120.00 <i>X</i>
9	Front wheel hub bearing LH	\$400.00 <i>X</i>
10	Front wheel shock absorber LH	\$520.00 <i>X</i>
11	Front Fog Lamp Trim LH	\$320.00 <i>X</i>
Total Cost of List Parts		\$8,290.00

Special Nett Items

No.	Description (Parts)	COST
1	Front Bumper Clips (1 set)	\$250.00 <i>3000</i>
2	Front Bumper Sensors (1 set)	\$600.00 <i>X</i>
3	Front Wheel Tyre LH	\$250.00 <i>X</i>
3	Front Wheel Sports Rim LH	\$800.00 <i>X</i>
Total Cost of Special Nett Items		\$1,900.00
TOTAL COST OF PARTS		\$10,190.00

Labour

No.	Description (Parts)	COST
1	To cut, weld, straighten affected areas and replace damaged parts.	\$1,200.00 <i>200</i>
2	To putty and spray painting the affected areas.	\$1,200.00 <i>500</i>
3	To check front lighting and wiring.	\$120.00 <i>20</i>
4	To apply anti rust proofing to the affected areas.	\$250.00 <i>30</i>
5	To remove and install front inner garnish and trim to facilitate the repair.	\$200.00 <i>X</i>
6	To conduct vehicle full diagnosis and fault findings to facilitate the repair.	\$400.00 <i>X</i>
7	To conduct wheel alignment	\$250.00 <i>X</i>
Total Cost of Labour		\$3,620.00
TOTAL COST OF REPAIR		\$13,810.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Taufik 97495749 / 62563561
wp 24/5/23 @ 1230

4/5 Resurvey after repair

Taufik @ Kantowu
3 days

- To check consistency of accident
- To check part prices