

ASS. REC. BY:

REF:

AW 23004834 / Key3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YP 33048

Yr Regn:

07, 18

Type: M.Car / M.Cycle / Bus / Van / Motor / Taxi / Prime Mover /

Truck / Trailer or

Make:

SUZUKI

NPR 75

c.c

5193

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

382825

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JAA NPR 7514G 7102394

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215 / 75 R17.5

R:

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pailun

Front

Rear

R/Bal.

9

mm

R/Bal.

22

mm

L/Bal.

9

mm

L/Bal.

22

mm

D.O.A.

9/5/23

D.O.I.

30/5/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 CIA & En not ready

2816 11 Pm @ 3100f. Confirmed. (Red 5624.19, 642)

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

11

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

3100f

TOTAL

SQM PTE LTD
BLK 1003 TOA PAYOH INDUSTRIAL PARK
05-1501 SINGAPORE 319075
SQM202088@GMAIL.COM

Not withstanding
Lump \$31000
Paying After Paying
4 days

Date : 30 May 2023

QUOTATION - THIRD PARTY INSURANCE

ALLIED WORLD ASSURANCE COMPANY

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 9 May 2023

VEH. No : YP 3304 Z / NPR75

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : LIBERTY INSURANCE

QTY	ITEM	AMOUNT	CONDITION
	YOUR INSURE : YM 5370 J		
1	FRONT RH DOOR 1120	\$ By 3,225.00	✓
1	FRONT RH DOOR WEATHERSTRIP 245-60	\$ Di/Red 385.00	50% 122.80
2	FRONT RH DOOR LOCK 325	\$ Red 480.00	✓
4	FRONT RH DOOR WINDOW GEAR	\$ Di/ 339.00	✓
1	FRONT RH DOOR GEAR MOTOR	\$ TM 318.90	✓
1	FRONT RH DOOR OUTER HANDLE	\$ R 298.00	X
2	FRONT RH DOOR TRIM BOARD 415	\$ My 668.00	✓
1	FRONT RH DOOR LAMP	\$ R 330.40	X
1	FRONT RH DOOR INNER RUBBER SEAL	\$ Di/ 298.00	✓
1	FRONT RH DOOR WINDOW FRAME RUBBER	\$ R 388.00	X
1	FRONT RH DOOR WINDOW CHANNEL	\$ Di/ 212.00	✓
1	FRONT RH DOOR PILLAR	REPAIR	
1	FRONT RH DOOR FRAME	REPAIR	
1	FRONT RH DOOR WHEELARCH GARNISH 280	\$ By 420.00	✓
1	FRONT RH DOOR SIDE PILLAR	REPAIR	
	TOTAL PARTS :	\$ 7,362.30	
	LESS 15%	\$ 368.12	
	TOTAL LIST PARTS :	\$ 6,994.19	
	<u>S/NETT</u>		
1SET	FRONT RH DOOR COMPANY STICKER	\$ R 800.00	250% ✓
	TOTAL PARTS PRICE :	\$ 6,994.19	

MOUNT BRING FORWARD :	\$	6,994.19	
about charges	\$	600.00	400
to transfer door parts to another door	\$	120.00	60
anti rust	\$	120.00	30
check door wiring system etc	\$	90.00	20
to do spray painting on affected area inner outer	\$	800.00	450
TOTAL LABOUR :	\$	1,730.00	
GRAND TOTAL PARTS & LABOUR :	\$	8,724.19	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: