



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 1 / 2

ESTIMATE

Date : 07/06/2023
To : LONPAC INSURANCE BHD.
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : CATHERINECHONGKL
Office / Mobile :
Email / Fax No. : CatherineChongKL@goldbell.com.sg

Reg No : WD4608C
Model : FS72HS2VDEA MIXER (C/C)
Chassis No : FS72HSA10001
Engine No : 470912C0503232
Quotation No. : 183093
Ref. No. : GBE/SVC/SALES-HQ/335-0405
D.O.A. : 04/05/2023
Policy No. : 5108173016-04
Claim Type : TP CLAIM - LONPAC INSURANCE
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		CABIN HEAD ASSY	bulv 1	128,250.00	-25	96,187.50	96,187.50
PARTS TOTAL :							96,187.50

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	\$600/day	6000	9000.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK		200	400.00
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	\$350/panel	2100	3500.00

LABOUR TOTAL :	12,900.00
SUB-TOTAL :	109,087.50
GST @ 8% for \$ 109,087.50	8,727.00
GRAND TOTAL (\$\$) :	117,814.50

Taufik 99495749
wp' 15/5/230 llaw
p/p Resurvey before parts
14 days
taufik e/llhantowr

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FUSO AIRMAN.

bigSAFE
S T R

