

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	TOPLIS AND HAR	DING (S) PTE LTD	Ref:	CS/TPS23004845/Rvy3
	133 CECIL STREE #17-01A		Date:	11/05/2023
	KECK SENG TOW	ER SINGAPORE 069535	Cada	TPS
1.		Delieu Deutieuleus	Code:	
1.				
	Insured Veh	EXCAVATOR BUCKET	Veh. Inspected	
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	VICTOR FONG	Assign Date	11/05/2023
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	04/05/2023	Inspection Date	12/05/2023
	Survey held at	GOLDBELL ENGINEERING PTE	LTD	
		10 TUAS AVE 18 SINGAPORE 638894		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				