

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLB 4151T
TP/ALLIANZ

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01 SINGAPORE 068897

Estimate No: ES2300495/WS
Date: 15 May 2023
Policy No: MA020982
Veh Reg No: SLB4151T
Make/Model: TOYOTA TOYOTA
COROLLA AXIO 1.5X A
Chassis No: NRE161003858
Engine No: 2NR8561966
Reg. Date: 06/04/2016

TEL: 67143369
ATTN: Motor Claim Department

WS Ref: TP/ALLIANZ
Claim Type: Third Party
Accident Date: 08/04/2023
TP Veh Reg No: GBL1775D

Estimate Repair Cost to Vehicle No :SLB4151T

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER RH SIDE RETAINER	62.20	1 PC	62.20	✓
2 HEADLAMP RH	1,050.00	1 PC	1,050.00	✓
3 HEADLAMP RH TOP PANEL	157.30	1 PC	157.30	✓
4 FRONT RH FENDER	833.00	1 PC	833.00	✓
5 FRT RH FENDER INNER SHIELD	179.00	1 PC	179.00	✓
6 FRONT RH FENDER INNER SHIELD CLIPS	3.50	6 PC	21.00	✓
7 FRONT WIPER TANK	157.50	1 PC	157.50	✓
8 FRONT GRILLE	323.30	1 PC	323.30	✓
9 FRONT GRILLE CLIPS	3.50	4 PC	14.00	✓
			2,797.30	
		Less 25%	699.33	2,097.98
Labour				
10 REMOVE AND REFIT FRT BUMPER ASSY, HEADLAMP, FRT RH FENDER, INN SHIELD. TO KNOCK, REPAIR FRT SUPPORT PANEL, WELD AND RENEW RH HEADLAMP PANEL AND REALIGN THE SAME.	600.00	1 LA	600.00	500
11 PUTTY AND RESPRAY FRT SUPPORT PANEL, FRT RH FENDER AND BONNET.	650.00	1 LA	650.00	400
12 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,280.00	1,280.00
			Total	S\$ 3,377.98
			Add GST @ 8%	270.24
			Total Amount Payable	S\$ 3,648.22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No title justification(s) is allowed
- Subject to any item(s) must be resurveyed and is subject to final approval from Insurance Company

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Accepted by Repairer

Date: