

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN CHAI HEE
BLK 153 YUNG HO ROAD #08-37
SINGAPORE 610153

Contact : 97641516

TAX INVOICE

Repair Code : CLM15903

Date in : 17/05/2023

Vehicle Num. : SML8378R

Model : KIA STONIC 1.0 DCT SR

Chassis/Eng# : KNAD6811VK6304606/G3LCKP041476

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Repa</i>	1	493.00	493.00
FRONT BUMPER INNER CENTER GRILLE <i>cit</i>	1	324.00	324.00
FRONT BUMPER LOWER GRILLE <i>new</i>	1	247.00	247.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	20.00	40.00
FRONT BUMPER SPONGE <i>could</i>	1	100.00	100.00
Subtotal before discount			1,204.00
Percentage discount 10%			120.40
Sub-total 1			1,083.60
FRONT BUMPER CAMERA <i>Repa</i>	1	800.00	800.00
FRONT BUMPER NUMBER PLATE <i>green</i>	1	25.00	25.00
FRONT BUMPER NUMBER PLATE HOLDER <i>green</i>	1	50.00	50.00
Subtotal before discount			875.00
Percentage discount 0%			0.00
Sub-total 2			875.00
Parts-total			1,958.60

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

60.00
500.00
400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN CHAI HEE
BLK 153 YUNG HO ROAD #08-37
SINGAPORE 610153

Contact : 97641516

TAX INVOICE

Repair Code : CLM15903

Date in : 17/05/2023

Vehicle Num. : SML8378R

Model : KIA STONIC 1.0 DCT SR

Chassis/Eng# : KNAD6811VK6304606/G3LCKP041476

To apply anti-rust chemical on repaired and replaced panel.

	4W	80.00
Labour Total		1,040.00
Parts & Labour Total		2,998.60

*** This is a computer-generated document which requires no signature.***

page 2

Adm G
L/S 17/05/23

02 Days.

total: 1625.30

L/S: 1.3K. ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: