

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23004866/SQY3Q2
Date: 07/06/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ005309
Claimant Vehicle No :	SHB4197J	Insured Vehicle No :	GBD8643Y
Date of Loss:	11/05/2023	Nature of Claim:	TP
		Claim No:	M2302940

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4197J	Engine No:	G4LEKU409568
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU190137
Reg. Date:	23/01/2020 (Man. Year: 2019)	Odometer:	229464 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,105.20	587.12	3,518.08	85.70
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,290.00	1,270.00	1,020.00	44.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,406.20	1,868.12	4,538.08	70.84
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	6,406.20	1,500.00	4,906.20	76.59
+ GST 8.00/8.00% (S\$)	512.50	120.00	392.50	76.59
Nett Amount (S\$)	6,918.70	1,620.00	5,298.70	76.59

INSPECTION

Date of Assignment:	11/05/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/05/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB4197J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR DOOR ASSY LH	Repair	2,147.90 FL	*- FL	
2	1		*REAR FENDER LH	Repair	1,768.30 FL	*- FL	
3	1		*REAR BUMPER ASSY	Not Necessary	459.40 FL	*- FL	
4	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL	
5	1		*REAR DOOR APPS LOGO	Necessary	80.00 F	*80.00 F	
6	1		*REAR FENDER PATROL STICKER	Necessary	30.00 F	*30.00 F	
7	1		*ADVERTISEMENT LOGO - DOOR	Necessary	100.00 F	*100.00 F	
8	1		*ADVERTISEMENT LOGO - FENDER	Necessary	100.00 F	*100.00 F	
9	1		*REAR WHEEL RIM CAP	Cut	346.40 FL	*346.40 FL	
					Sub Total (\$\$)	5,054.00	656.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	948.80	69.28
					Total Parts (\$\$)	4,105.20	587.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAYPAINT	New	800.00	500.00
3	TUFF KOTE	New	50.00	0.00
4	REMOVE/REFIX REAR UPHOLSTERY	New	120.00	30.00
5	REMOVE/REFIX DOOR PARTS	New	120.00	40.00
			Gross Labour Cost (\$\$)	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >