

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tang Hock Lye Ben

Date: 31 May 2023

Preliminary Advice

Insured Vehicle No : GBD8643Y
TP Vehicle No : SHB4197J Accident Date : 11/05/2023
Make : HYUNDAI IONIQ HYBRID Assignment Date : 11/05/2023
Date of Inspection : 12/05/2023 Est. Duration of Repair : 3
Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)
59 LOYANG DRIVE
SINGAPORE 508969

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 6,406.20 |
| Revised Amount | :S\$ | 1,868.12 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 1,868.12 |
| Lump Sum Repair | :S\$ | 1,500.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.