

Date : 07/04/2023
Vehicle No: SMT5825U
Model: FORD MUSTANG 5.0GT AUTO
Chassis: 1FA6P8NF2J5141003
Reg.Year: 2020
Policy No: DMPCSNW00158392200
Date of Accident: 28/02/2023
Estimator: VICTOR

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER COVER	1		\$4,800.00
2	FRONT BUMPER LOWER GRILLE	1		\$400.00
3	FRONT BUMPER VALANCE PANEL	1		\$1,500.00
4	FRONT BUMPER OUTER GRILLE LH	1		\$150.00
5	FRONT BUMPER OUTER GRILLE RH	1		\$150.00
6	FRONT BUMPER IMPACT ABSORBER	1		\$250.00
7	FRONT BUMPER IMPACT BAR	1		\$1,500.00
8	FRONT GRILLE	1		\$1,200.00
9	FRONT GRILLE EMBLEM (CHROME)	1		\$30.00
10	FRONT BONNET	1		\$8,000.00
11	FRONT BONNET STRIKER	1		\$100.00
12	FRONT BONNET INSULATOR	1		\$1,500.00
13	FRONT BONNET SUPPORT ROD	1		\$160.00
14	FRONT BONNET HINGE LH	1		\$310.00
15	FRONT BONNET HINGE RH	1		\$310.00
16	FRONT BONNET INSULATOR CLIP (SET)	1		\$120.00
17	FRONT BONNET REAR SEAL	1		\$220.00
18	FRONT BONNET SIDE SEAL	1		\$320.00
19	FRONT BONNET FRONT SEAL	1		\$400.00
20	FRONT BONNET LATCH	1		\$320.00
21	FRONT BONNET RELEASE HANDLE	1		\$100.00
22	FRONT BONNET SCOPE	2	\$800.00	\$1,600.00
23	ENGINE COVER	1		\$1,400.00
24	ENGINE COVER CAP	2	\$180.00	\$360.00
25	AIR CLEANER ASSY	1		\$1,600.00
26	AIR FILTER	1		\$150.00
27	BATTERY TRAY	1		\$700.00
28	BATTERY TRAY SUPPORT	1		\$50.00
29	FRONT FENDER RH (GT MODEL)	1		\$5,000.00
30	FRONT FENDER BRACKET RH	1		\$200.00
31	FRONT FENDER REAR INSULATOR RH	1		\$200.00
32	FRONT FENDER INSULATOR PAD RH	1		\$150.00
33	FRONT FENDER LINER RH			\$300.00

Head office

8 Kung Chong Road Singapore 169143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 560047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 07/04/2023
Vehicle No: SMT5825U
Model: FORD MUSTANG 5.0GT AUTO
Chassis: 1FA6P8NF2J5141003
Reg.Year: 2020
Policy No: DMPCSNW00158392200
Date of Accident: 28/02/2023

34	FRONT FENDER 5.0 EMBLEM (CHROME)	1		\$200.00
35	FRONT COWL GRILLE	1		\$1,100.00
36	FRONT UPPER TIE BAR	1		\$1,500.00
37	FRONT SIGHT SHIELD	1		\$400.00
38	FRONT UPPER DEFLECTOR	1		\$450.00
39	FRONT SIDE AIR BAFLE RH	1		\$380.00
40	FRONT SIDE AIR BAFLE LH	1		\$380.00
41	FRONT AIR DEFLECTOR RH	1		\$100.00
42	FRONT AIR DEFLECTOR LH	1		\$100.00
43	RADIATOR CONTROL SHUTTER ASSY	1		\$900.00
44	FRONT RADIATOR LOWER DEFLECTOR	1		\$380.00
45	FRONT ENGINE UNDER COVER	1		\$800.00
46	RADIATOR CORE SUPPORT INSULATOR	1		\$400.00
47	FRONT UPPER RAIL ASSY RH	1		\$550.00
48	FRONT UPPER RAIL FENDER	1		\$120.00
49	FRONT FENDER CROSS BAR RH	1		\$600.00
50	FRONT LOWER RAIL ASSY RH	1		\$500.00
51	FRONT LOWER FRONT BRACKET RH	1		\$220.00
52	FRONT LOWER RAIL REINFORCED RH	1		\$5,400.00
53	FRONT UPPER REINFORCED RH	1		\$250.00
54	FRONT UPPER SUPPORT PLATE RH	1		\$250.00
55	FRONT FENDER TIE BAR RH	1		\$400.00
56	RADIATOR GRILLE SUPPORT BRACE RH	1		\$400.00
57	WIPER WASHER RESERVOIR	1		\$480.00
58	RADIATOR ASSY	1		\$1,400.00
59	RADIATOR UPPER HOSE	1		\$400.00
60	RADIATOR LOWER HOSE	1		\$350.00
61	RADIATOR UPPER BRACKET	1	\$80.00	\$160.00
62	RADIATOR UPPER INSULATOR	2	\$50.00	\$100.00
63	RADIATOR LOWER INSULATOR	2	\$50.00	\$100.00
64	AIR CON CONDENSER	1		\$1,500.00
65	AIR CON CONDENSER ACCUMULATOR	1		\$200.00
66	AMBIENT TEMPERATURE SENSOR	1		\$40.00
67	RADIATOR COOLING FAN ASSY	1		\$1,300.00
68	TRANSMISSION OIL COOLER ASSY	1		\$1,000.00
69	FRONT HEADLAMP ASSY RH	1		\$4,500.00
70	FRONT HEADLAMP ASSY LH	1		\$4,500.00

Head office

8 Kung Chong Road Singapore 169143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 551500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 07/04/2023
Vehicle No: SMT5825U
Model: FORD MUSTANG 5.0GT AUTO
Chassis: 1FA6P8NF2J5141003
Reg.Year: 2020
Policy No: DMPCSNW00158392200
Date of Accident: 28/02/2023

71	FRONT MARKER / PARK LAMP ASSY RH	1		\$2,600.00
72	FRONT WINDSHIELD GLASS	1		\$7,500.00
73	RAIN SENSOR	1		\$750.00
74	REAR BUMPER COVER	1		\$4,000.00
75	REAR BUMPER VALANCE PANEL	1		\$1,500.00
76	REAR BUMPER REFLECTOR LH	1		\$80.00
77	REAR BUMPER INNER SUPPORT	1		\$480.00
78	REAR BUMPER SIDE BRACKET LH	1		\$200.00
79	REAR BUMPER STAY BRACKET LH	1		\$200.00
80	REAR BUMPER END SUPPORT LH	1		\$200.00
81	REAR BUMPER MOUNT BRACKET LH	1		\$200.00
82	REAR BUMPER CENTER SUPPORT	1		\$150.00
83	REAR TAIL LAMP ASSY LH	1		\$3,500.00
84	REAR TAIL LAMP SHIELD LH	1		\$150.00
85	REAR FENDER LH	1		\$11,000.00
86	REAR QUARTER GLASS LH	1		\$700.00
87	FUEL POCKET	1		\$300.00
88	FUEL DOOR	1		\$200.00
89	REAR WHEEL HOUSE LINER LH	1		\$400.00
90	REAR BOOT			\$8,000.00
91	HEAD AIRBAG RH	1		\$4,000.00
92	DRIVER AIRBAG	1		\$6,600.00
93	KNEE AIRBAG RH	1		\$4,200.00
94	FRONT SEAT AIRBAG RH	1		\$5,700.00
95	AIRBAG CONTROL MODULE	1		\$2,800.00
96	STEERING WHEEL	1		\$3,000.00
97	STEERING WHEEL CONTROL	1		\$1,500.00
98	STEERING WHEEL CLOCK SPRING	1		\$600.00
99	FRONT IMPACT SENSOR	4	\$320.00	\$1,280.00
100	SIDE IMPACT SENSOR RH	1		\$150.00
101	AIRBAG POSITION SENSOR RH	1		\$180.00
102	STEERING CRUISE SWITCH RH	1		\$1,550.00
103	STEERING UPPER SHROUD	1		\$180.00
104	STEERING LOWER SHROUD	1		\$180.00
105	FRONT SEAT BELT ASSY RH	1		\$1,000.00
106	FRONT SEAT BELT BUCKLE	2	\$450.00	\$900.00
107	FRONT SEAT BELT ASSY LH	1		\$1,000.00

Head office

8 Kung Chong Road Singapore 169143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 07/04/2023
Vehicle No: SMT5825U
Model: FORD MUSTANG 5.0GT AUTO
Chassis: 1FA6P8NF2J5141003
Reg.Year: 2020
Policy No: DMPCSNW00158392200
Date of Accident: 28/02/2023

108	REAR SEAT BELT	2	\$1,000.00	\$2,000.00
109	FRONT RECARDO SEAT	1		\$8,500.00
110	FRONT WHEEL RIM LH 19"	2	\$5,000.00	\$10,000.00
111	FRONT WIRE HARNESS			\$10,500.00
			SUB TOTAL	\$173,290.00
			LESS 5%	\$8,664.50
			PARTS TOTAL	\$164,625.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	MICHELIN PILOT SPORT 4S - 255/40ZR19	2	\$600.00	\$1,200.00
2	FRONT BUMPER CLIPS	1		\$150.00
3	FRONT GRILLE CLIPS	1		\$100.00
4	FRONT LOWER GRILLE CLIPS	1		\$100.00
5	FRONT INNNER SHIELD CLIPS	1		\$100.00
6	FRONT UNDERCOVER CLIPS	1		\$150.00
7	FRONT LICENSE PLATE	1		\$30.00
8	FRONT LICENSE PLATE HOLDER	1		\$50.00
			S/N TOTAL	\$1,880.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREA.	\$6,000.00
LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS.	\$4,000.00
LABOUR CHARGES TO INSTALL FRONT AIRBAG SYSTEM.	\$1,000.00
LABOUR CHARGES TO REMOVE & REFIX FRONT WINDSCREEN.	\$300.00
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN.	\$300.00
LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS.	\$150.00

Head office

6 Kung Chong Road Singapore 169143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 07/04/2023
Vehicle No: SMT5825U
Model: FORD MUSTANG 5.0GT AUTO
Chassis: 1FA6P8NF2J5141003
Reg.Year: 2020
Policy No: DMPCSNW00158392200
Date of Accident: 28/02/2023

TO WHEEL ALIGNMENT & BALANCING.	\$250.00
TO TUFF KOTE/ANTI-RUST & ETC.	\$500.00
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$1,000.00
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$500.00

LABOUR TOTAL	\$14,000.00
--------------	-------------

TOTAL	\$180,505.50
--------------	---------------------

Head office

8 Kung Chong Road Singapore 169143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

