

Date : 07/04/2023  
Vehicle No: SMT5825U  
Model: FORD MUSTANG 5.0GT AUTO  
Chassis: 1FA6P8NF2J5141003  
Reg.Year: 2020  
Policy No: DMPCSNW00158392200  
Date of Accident: 28/02/2023  
Estimator: VICTOR

Not Authorized  
L1 Eng &  
Penny After Paint  
36class

## ESTIMATE

| NO. | DESCRIPTION                       | QTY | UNIT S\$       | AMOUNT S\$ |
|-----|-----------------------------------|-----|----------------|------------|
| 1   | FRONT BUMPER COVER                | 1   | Rd             | \$4,800.00 |
| 2   | FRONT BUMPER LOWER GRILLE         | 1   | CM             | \$400.00   |
| 3   | FRONT BUMPER VALANCE PANEL        | 1   | R1             | \$1,500.00 |
| 4   | FRONT BUMPER OUTER GRILLE LH      | 1   |                | \$150.00   |
| 5   | FRONT BUMPER OUTER GRILLE RH      | 1   | h17            | \$150.00   |
| 6   | FRONT BUMPER IMPACT ABSORBER      | 1   | CM             | \$250.00   |
| 7   | FRONT BUMPER IMPACT BAR           | 1   |                | \$1,500.00 |
| 8   | FRONT GRILLE                      | 1   | CM             | \$1,200.00 |
| 9   | FRONT GRILLE EMBLEM (CHROME)      | 1   | RM             | \$30.00    |
| 10  | FRONT BONNET                      | 1   | R1             | \$8,000.00 |
| 11  | FRONT BONNET STRIKER              | 1   | R1             | \$100.00   |
| 12  | FRONT BONNET INSULATOR            | 1   | Refom          | \$1,500.00 |
| 13  | FRONT BONNET SUPPORT ROD          | 1   | n              | \$160.00   |
| 14  | FRONT BONNET HINGE LH             | 1   | R1             | \$310.00   |
| 15  | FRONT BONNET HINGE RH             | 1   | R1             | \$310.00   |
| 16  | FRONT BONNET INSULATOR CLIP (SET) | 1   | RM             | \$120.00   |
| 17  | FRONT BONNET REAR SEAL            | 1   |                | \$220.00   |
| 18  | FRONT BONNET SIDE SEAL            | 1   |                | \$320.00   |
| 19  | FRONT BONNET FRONT SEAL           | 1   |                | \$400.00   |
| 20  | FRONT BONNET LATCH                | 1   | R1             | \$320.00   |
| 21  | FRONT BONNET RELEASE HANDLE       | 1   |                | \$100.00   |
| 22  | FRONT BONNET SCOPE                | 2   | OL/SH \$800.00 | \$1,600.00 |
| 23  | ENGINE COVER                      | 1   | CM             | \$1,400.00 |
| 24  | ENGINE COVER CAP                  | 2   | \$180.00       | \$360.00   |
| 25  | AIR CLEANER ASSY                  | 1   | m3cm           | \$1,600.00 |
| 26  | AIR FILTER                        | 1   |                | \$150.00   |
| 27  | BATTERY TRAY                      | 1   |                | \$700.00   |
| 28  | BATTERY TRAY SUPPORT              | 1   |                | \$50.00    |
| 29  | FRONT FENDER RH (GT MODEL)        | 1   | R1             | \$5,000.00 |
| 30  | FRONT FENDER BRACKET RH           | 1   | R1             | \$200.00   |
| 31  | FRONT FENDER REAR INSULATOR RH    | 1   | RM             | \$200.00   |
| 32  | FRONT FENDER INSULATOR PAD RH     | 1   | RM             | \$150.00   |
| 33  | FRONT FENDER LINER RH             |     | Tn             | \$300.00   |

### Head office

5 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 551500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1893

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 580047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 07/04/2023  
Vehicle No: SMT5825U  
Model: FORD MUSTANG 5.0GT AUTO  
Chassis: 1FA6P8NF2J5141003  
Reg.Year: 2020  
Policy No: DMPCSNW00158392200  
Date of Accident: 28/02/2023

|    |                                  |   |         |            |   |
|----|----------------------------------|---|---------|------------|---|
| 34 | FRONT FENDER 5.0 EMBLEM (CHROME) | 1 |         | \$200.00   | ✓ |
| 35 | FRONT COWL GRILLE                | 1 |         | \$1,100.00 | ✓ |
| 36 | FRONT UPPER TIE BAR              | 1 |         | \$1,500.00 | ✓ |
| 37 | FRONT SIGHT SHIELD               | 1 |         | \$400.00   | ✓ |
| 38 | FRONT UPPER DEFLECTOR            | 1 |         | \$450.00   | ✓ |
| 39 | FRONT SIDE AIR BAFLE RH          | 1 |         | \$380.00   | ✓ |
| 40 | FRONT SIDE AIR BAFLE LH          | 1 |         | \$380.00   | ✓ |
| 41 | FRONT AIR DEFLECTOR RH           | 1 |         | \$100.00   | ✓ |
| 42 | FRONT AIR DEFLECTOR LH           | 1 |         | \$100.00   | ✓ |
| 43 | RADIATOR CONTROL SHUTTER ASSY    | 1 |         | \$900.00   | ✓ |
| 44 | FRONT RADIATOR LOWER DEFLECTOR   | 1 |         | \$380.00   | ✓ |
| 45 | FRONT ENGINE UNDER COVER         | 1 |         | \$800.00   | ✓ |
| 46 | RADIATOR CORE SUPPORT INSULATOR  | 1 |         | \$400.00   | ✓ |
| 47 | FRONT UPPER RAIL ASSY RH         | 1 |         | \$550.00   | ✓ |
| 48 | FRONT UPPER RAIL FENDER          | 1 |         | \$120.00   | ✓ |
| 49 | FRONT FENDER CROSS BAR RH        | 1 |         | \$600.00   | ✓ |
| 50 | FRONT LOWER RAIL ASSY RH         | 1 |         | \$500.00   | ✓ |
| 51 | FRONT LOWER FRONT BRACKET RH     | 1 |         | \$220.00   | ✓ |
| 52 | FRONT LOWER RAIL REINFORCED RH   | 1 |         | \$5,400.00 | X |
| 53 | FRONT UPPER REINFORCED RH        | 1 |         | \$250.00   | ✓ |
| 54 | FRONT UPPER SUPPORT PLATE RH     | 1 |         | \$250.00   | ✓ |
| 55 | FRONT FENDER TIE BAR RH          | 1 |         | \$400.00   | ✓ |
| 56 | RADIATOR GRILLE SUPPORT BRACE RH | 1 |         | \$400.00   | ✓ |
| 57 | WIPER WASHER RESERVOIR           | 1 |         | \$480.00   | ✓ |
| 58 | RADIATOR ASSY                    | 1 |         | \$1,400.00 | ✓ |
| 59 | RADIATOR UPPER HOSE              | 1 |         | \$400.00   | ✓ |
| 60 | RADIATOR LOWER HOSE              | 1 |         | \$350.00   | ✓ |
| 61 | RADIATOR UPPER BRACKET           | 1 | \$80.00 | \$160.00   | ✓ |
| 62 | RADIATOR UPPER INSULATOR         | 2 | \$50.00 | \$100.00   | ✓ |
| 63 | RADIATOR LOWER INSULATOR         | 2 | \$50.00 | \$100.00   | ✓ |
| 64 | AIR CON CONDENSER                | 1 |         | \$1,500.00 | ✓ |
| 65 | AIR CON CONDENSER ACCUMULATOR    | 1 |         | \$200.00   | ✓ |
| 66 | AMBIENT TEMPERATURE SENSOR       | 1 |         | \$40.00    | ✓ |
| 67 | RADIATOR COOLING FAN ASSY        | 1 |         | \$1,300.00 | ✓ |
| 68 | TRANSMISSION OIL COOLER ASSY     | 1 |         | \$1,000.00 | ✓ |
| 69 | FRONT HEADLAMP ASSY RH           | 1 |         | \$4,500.00 | ✓ |
| 70 | FRONT HEADLAMP ASSY LH           | 1 |         | \$4,500.00 | ✓ |

#### Head office

5 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1983

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 580047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 07/04/2023  
Vehicle No: SMT5825U  
Model: FORD MUSTANG 5.0GT AUTO  
Chassis: 1FA6P8NF2J5141003  
Reg.Year: 2020  
Policy No: DMPCSNW00158392200  
Date of Accident: 28/02/2023

|     |                                  |   |          |             |
|-----|----------------------------------|---|----------|-------------|
| 71  | FRONT MARKER / PARK LAMP ASSY RH | 1 |          | \$2,600.00  |
| 72  | FRONT WINDSHIELD GLASS           | 1 |          | \$7,500.00  |
| 73  | RAIN SENSOR                      | 1 |          | \$750.00    |
| 74  | REAR BUMPER COVER                | 1 |          | \$4,000.00  |
| 75  | REAR BUMPER VALANCE PANEL        | 1 |          | \$1,500.00  |
| 76  | REAR BUMPER REFLECTOR LH         | 1 |          | \$80.00     |
| 77  | REAR BUMPER INNER SUPPORT        | 1 |          | \$480.00    |
| 78  | REAR BUMPER SIDE BRACKET LH      | 1 |          | \$200.00    |
| 79  | REAR BUMPER STAY BRACKET LH      | 1 |          | \$200.00    |
| 80  | REAR BUMPER END SUPPORT LH       | 1 |          | \$200.00    |
| 81  | REAR BUMPER MOUNT BRACKET LH     | 1 |          | \$200.00    |
| 82  | REAR BUMPER CENTER SUPPORT       | 1 |          | \$150.00    |
| 83  | REAR TAIL LAMP ASSY LH           | 1 |          | \$3,500.00  |
| 84  | REAR TAIL LAMP SHIELD LH         | 1 |          | \$150.00    |
| 85  | REAR FENDER LH                   | 1 |          | \$11,000.00 |
| 86  | REAR QUARTER GLASS LH            | 1 |          | \$700.00    |
| 87  | FUEL POCKET                      | 1 |          | \$300.00    |
| 88  | FUEL DOOR                        | 1 |          | \$200.00    |
| 89  | REAR WHEEL HOUSE LINER LH        | 1 |          | \$400.00    |
| 90  | REAR BOOT                        |   |          | \$8,000.00  |
| 91  | HEAD AIRBAG RH                   | 1 |          | \$4,000.00  |
| 92  | DRIVER AIRBAG                    | 1 |          | \$6,600.00  |
| 93  | KNEE AIRBAG RH                   | 1 |          | \$4,200.00  |
| 94  | FRONT SEAT AIRBAG RH             | 1 |          | \$5,700.00  |
| 95  | AIRBAG CONTROL MODULE            | 1 |          | \$2,800.00  |
| 96  | STEERING WHEEL                   | 1 |          | \$3,000.00  |
| 97  | STEERING WHEEL CONTROL           | 1 |          | \$1,500.00  |
| 98  | STEERING WHEEL CLOCK SPRING      | 1 |          | \$600.00    |
| 99  | FRONT IMPACT SENSOR              | 4 | \$320.00 | \$1,280.00  |
| 100 | SIDE IMPACT SENSOR RH            | 1 |          | \$150.00    |
| 101 | AIRBAG POSITION SENSOR RH        | 1 |          | \$180.00    |
| 102 | STEERING CRUISE SWITCH RH        | 1 |          | \$1,550.00  |
| 103 | STEERING UPPER SHROUD            | 1 |          | \$180.00    |
| 104 | STEERING LOWER SHROUD            | 1 |          | \$180.00    |
| 105 | FRONT SEAT BELT ASSY RH          | 1 |          | \$1,000.00  |
| 106 | FRONT SEAT BELT BUCKLE           | 2 | \$450.00 | \$900.00    |
| 107 | FRONT SEAT BELT ASSY LH          | 1 |          | \$1,000.00  |

#### Head office

8 Kung Chong Road Singapore 169143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9819 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 07/04/2023  
Vehicle No: SMT5825U  
Model: FORD MUSTANG 5.0GT AUTO  
Chassis: 1FA6P8NF2J5141003  
Reg.Year: 2020  
Policy No: DMPCSNW00158392200  
Date of Accident: 28/02/2023

|     |                        |   |            |                      |              |
|-----|------------------------|---|------------|----------------------|--------------|
| 108 | REAR SEAT BELT         | 2 | \$1,000.00 | <i>Sn</i> \$2,000.00 | <i>X</i>     |
| 109 | FRONT RECARDO SEAT     | 1 |            | <i>Sn</i> \$8,500.00 | <i>✓</i>     |
| 110 | FRONT WHEEL RIM LH 19" | 2 | \$5,000.00 | \$10,000.00          | <i>?</i>     |
| 111 | FRONT WIRE HARNESS     |   |            | \$10,500.00          | <i>?</i>     |
|     |                        |   |            | SUB TOTAL            | \$173,290.00 |
|     |                        |   |            | LESS 5%              | \$8,664.50   |
|     |                        |   |            | PARTS TOTAL          | \$164,625.50 |

| NO. | SPECIAL NETT                         | QTY | UNIT S\$ | AMOUNT S\$         |              |
|-----|--------------------------------------|-----|----------|--------------------|--------------|
| 1   | MICHELIN PILOT SPORT 4S - 255/40ZR19 | 2   | \$600.00 | \$1,200.00         | <i>?</i>     |
| 2   | FRONT BUMPER CLIPS                   | 1   |          | <i>mc</i> \$150.00 | <i>—</i>     |
| 3   | FRONT GRILLE CLIPS                   | 1   |          | <i>mc</i> \$100.00 | <i>—</i>     |
| 4   | FRONT LOWER GRILLE CLIPS             | 1   |          | <i>mc</i> \$100.00 | <i>—</i>     |
| 5   | FRONT INNER SHIELD CLIPS             | 1   |          | <i>mc</i> \$100.00 | <i>—</i>     |
| 6   | FRONT UNDERCOVER CLIPS               | 1   |          | <i>mc</i> \$150.00 | <i>—</i>     |
| 7   | FRONT LICENSE PLATE                  | 1   |          | <i>mc</i> \$30.00  | <i>} 450</i> |
| 8   | FRONT LICENSE PLATE HOLDER           | 1   |          | \$50.00            |              |
|     |                                      |     |          | S/N TOTAL          | \$1,880.00   |

## LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREA.

*3600*  
\$6,000.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS.

\$4,000.00 *2500*

LABOUR CHARGES TO INSTALL FRONT AIRBAG SYSTEM.

\$1,000.00 *500*

LABOUR CHARGES TO REMOVE & REFIX FRONT WINDSCREEN.

\$300.00 *1200*

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN.

\$300.00 *1200*

LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS.

\$150.00 *800*

### Head office

5 Kung Chong Road Singapore 169143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 07/04/2023  
Vehicle No: SMT5825U  
Model: FORD MUSTANG 5.0GT AUTO  
Chassis: 1FA6P8NF2J5141003  
Reg.Year: 2020  
Policy No: DMPCSNW00158392200  
Date of Accident: 28/02/2023

|                                            |            |              |
|--------------------------------------------|------------|--------------|
| TO WHEEL ALIGNMENT & BALANCING.            | \$250.00   | 1201         |
| TO TUFF KOTE/ANTI-RUST & ETC.              | \$500.00   | N2 X         |
| TO DIAGNOSIS FAULT CODE & RESET MEMORY.    | \$1,000.00 | ?            |
| TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. | \$500.00   | 2001         |
| LABOUR TOTAL                               |            | \$14,000.00  |
| TOTAL                                      |            | \$180,505.50 |

## Head office

5 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

## Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

## Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 560047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

