

## Vehicle Damage Assessment Report for [SMY6079Z]

Estimate Created: 23/05/2023 14:38 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

Owned: 23/05/2023 14:51 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

### General Information

---

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

### Vehicle Information

---

Brand	Nissan	Model	Qashqai
Engine Type			
License Plate Number	SMY6079Z	VIN (or Chassis #)	

### Vehicle Condition

---

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

### Comments

---

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$5,500.00 WITH 6 WORKING  
DAYS

Insurlogic 4 (23/05/2023 14:51)

**Parts**

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear bumper		1	755.40	-10.00 %	679.86
Rear bumper side holder		1	35.90	-10.00 %	32.31
Taillamp		1	323.70	-10.00 %	291.33
Taillamp panel		1	0.00	-10.00 %	0.00
Rear fender		1	1081.40	-10.00 %	973.26
Rear fender arc garnish		1	483.10	-10.00 %	434.79
Rear fender inner shield		1	202.10	-10.00 %	181.89
Rear fender air vent		1	62.80	-10.00 %	56.52
Rear door		1	1166.40	-10.00 %	1,049.76
Rear door lock		1	196.70	-10.00 %	177.03
Rear door inner trim board		1	844.40	-10.00 %	759.96
Rear door glass regulator c/w motor		1	487.90	-10.00 %	439.11
Rear alarm		1	102.40	-10.00 %	92.16
Parts Subtotal					5,167.98

**Materials**

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear bumper clips		1.0	30.00	0.00 %	30.00
Rear fender arc garnish		1.0	20.00	0.00 %	20.00
Rear fender inner shield clips		1.0	30.00	0.00 %	30.00
Rear fender inner trim board clips		1.0	30.00	0.00 %	30.00
Materials Subtotal					110.00

**Labor**

## Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	800.00	0.00 %	800.00
Wiring check	RnR	30.00	0.00 %	30.00
To apply tuff coat	RnR	60.00	0.00 %	60.00
To remove upholstery	RnR	60.00	0.00 %	60.00
To transfer door fittings	RnR	60.00	0.00 %	60.00
To remove reverse sensor.	RnR	50.00	0.00 %	50.00

**Paint**

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	600.00	0.00 %	600.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	1,060.00
			Paint Labor Subtotal	600.00
			Labor Subtotal	1,660.00

**Summary**

Repair Cost	6,937.98
Discount(20 %)	(1,387.60)
	5,550.38
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,550.38