

SIN YU SIN WORKSHOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SMY6079Z 2017 JULY
VEHICLE MODEL : NISSAN QASHQAI 1.2
CHASSIS NO : SJNFEAJ11U1915749

TP Ergo
Veron.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>torn</i>	1	\$ 755.40	\$ 755.40
2	REAR BUMPER SIDE HOLDER <i>2nd</i>	1	\$ 35.90	\$ 35.90
3	TAILLAMP <i>cracked</i>	1	\$ 323.70	\$ 323.70
4	TAILLAMP PANEL <i>Repair</i>	1	\$ 192.30	\$ 192.30
5	REAR FENDER <i>Distorted</i>	1	\$ 1,081.40	\$ 1,081.40
6	REAR FENDER ARC GARNISH <i>cut</i>	1	\$ 483.10	\$ 483.10
7	REAR FENDER INNER TRIM BOARD <i>new</i>	1	\$ 361.70	\$ 361.70
8	REAR FENDER INNER SHIELD <i>torn</i>	1	\$ 202.10	\$ 202.10
9	REAR FENDER AIR VENT <i>cracked</i>	1	\$ 62.80	\$ 62.80
10	REAR DOOR <i>Deleted</i>	1	\$ 1,166.40	\$ 1,166.40
11	REAR DOOR LOCK <i>2nd</i>	1	\$ 196.70	\$ 196.70
12	REAR DOOR WEATHERSTRIPE <i>new</i>	1	\$ 187.40	\$ 187.40
13	REAR DOOR INNER TRIM BOARD <i>cracked</i>	1	\$ 844.40	\$ 844.40
14	REAR DOOR GLASS REGULATOR C/W MOTOR <i>2nd</i>	1	\$ 487.90	\$ 487.90
15	REAR ALARM <i>cracked</i>	1	\$ 102.40	\$ 102.40
16	TAILGATE REFLECTOR <i>new</i>	1	\$ 235.40	\$ 235.40

TOTAL PRICE: \$ 6,719.00
LESS 10% \$ 671.90
SUB TOTAL PRICE: \$ 6,047.10

5742.20
5167.98

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS	1 SET	\$ 30.00	\$ 30.00
2	REAR FENDER ARC GARNISH <i>2 new</i>	1 SET	\$ 20.00	\$ 20.00
3	REAR FENDER INNER SHIELD CLIPS	1 SET	\$ 30.00	\$ 30.00
4	REAR FENDER INNER TRIM BOARD CLIPS	1 SET	\$ 30.00	\$ 30.00
5	REAR DOOR BLACK TAPE <i>new</i>	1	\$ 60.00	\$ 60.00
6	REAR WHEEL RIM <i>3 new</i>	1	\$ 780.00	\$ 780.00
7	REAR TYRE <i>1 new</i>	1	\$ 250.00	\$ 250.00

TOTAL : \$ 1,200.00

110

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	600	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE UPHOLSTERY	\$ 150.00	60	

6	TO TRANSFER DOOR FITTINGS	\$ 150.00	60.	
7	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	X	
8	TO REMOVE REVERSE SENSOR	\$ 100.00	50.	
		\$ 2,950.00	1660	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,247.10
 TOTAL LABOUR COST: \$ 2,950.00
 TOTAL REPAIR COST: \$ 10,197.10

Total: 6937.98.
 L/S: 5.5K
 06 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:
 NO. OF DAYS:

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: