



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS3/SMO23004878/y3

Date: 12/05/2023

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBC 9267Z	Veh. Inspected	SKB 894X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2301839/SYH	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	12/05/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/05/2023	Inspection Date	
Survey held at	TRIDENT AUTO SERVICE CENTRE PTE LTD 8 KAKI BUKIT AVENUE 4, #02-42, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.