



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23004883/Kqy3e2	Date: 30/05/2023
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMS 6626B	Veh. Inspected	SKA 6065M	
Policy No.	P10229827R03	Coverage (\$)	0.00	
Claim No.	C10022130 /JL	Excess (\$)	0.00	
Assign From	LEONG ENG MING	Assign Date	12/05/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUZUKI SWIFT (A)	c.c	1586	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JSAEZC31S00206268	Colour	MATT GREY	
Odometer	204764 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	BRIDGESTONE	3 mm	
L/H Front Tyre	195/50 R16	BRIDGESTONE	3 mm	
R/H Rear Tyre	195/50 R16	TOURADOR	4 mm	
L/H Rear Tyre	195/50 R16	TOURADOR	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/05/2023	Inspection Date	17/05/2023	
Survey held at	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		