



QUOTATION

Customer :

NO. : 43490

- Rev. 1

ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

DATE : 11/05/2023
CLAIM NO. : 12182
POLICY NO. : MC/01009116/01

ATTN: MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBN1336C
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
2	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$59.00 Disc %: 10.00	53.10
3	COVER SIDE LH (GREY) P/N: 60877 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00 Disc %: 10.00	37.80
4	COVER SIDE LOWER LH (WHITE) P/N: 58097 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00 Disc %: 10.00	22.50
5	COVER SIDE LOWER RH (WHITE) P/N: 58117 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00 Disc %: 10.00	22.50
6	COVER SIDE REAR RH (WHITE) P/N: 58102 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00 Disc %: 10.00	29.70
7	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00 Disc %: 10.00	32.40
8	COWLING FRONT RH (WHITE) P/N: 59594 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00 Disc %: 10.00	32.40
9	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$17.00 Disc %: 10.00	30.60

*43490 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
10	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$170.00	170.00
11	MUDGUARD FRONT (WHITE) P/N: 58087 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80
12	PANEL 1 (GREY) LH P/N: 59584 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00 Disc %: 10.00	22.50
13	PANEL 2 (GREY) RH P/N: 58081 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00 Disc %: 10.00	22.50
14	SPRAY LACQUER ON COVER CENTRE LH - (REPORTED BY MECHANIC)	Spray	1.00	\$100.00	100.00
15	SPRAY LACQUER ON COVER SIDE REAR RH - (REPORTED BY MECHANIC)	Spray	1.00	\$70.00	70.00
16	SPRAY LACQUER ON COWLING FRONT LH - (REPORTED BY MECHANIC)	Spray	1.00	\$100.00	100.00
17	SPRAY LACQUER ON COWLING FRONT RH - (REPORTED BY MECHANIC)	Spray	1.00	\$100.00	100.00
18	SPRAY LACQUER ON MUDGUARD FRONT - (REPORTED BY MECHANIC)	Spray	1.00	\$55.00	55.00
19	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH P/N: 61181 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00
20	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
21	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
22	STICKER (CISCO) COWLING FRONT RH P/N: 58617 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
23	STICKER (CISCO) LINING COVER REAR LH P/N: 61573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
24	STICKER (CISCO) MUDGUARD FRONT P/N: 58618 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00

*43490 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
25	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$35.00	35.00
SUB TOTAL					\$1,243.00
GST @ 8 %					\$99.44
GRAND TOTAL (SGD)					\$1,342.44

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*43490 *

