

F-1 AUTOCLINIC PTE LTD

25 KAKI BUKIT ROAD4 # 05-26 SYNERGY @KB Singapore 417800

TP Allianz.

Xiao Tony.

LIO HEE FONG
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

15th MAY 2023

J776620W6J003098

Accident date: 25th APRIL 2023

Estimated repair cost for vehicle no: SKW6777B TOYOTA WISH 1.8 A CVT '2015'

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,558.00 1280
2	2	Rear Boot Lid Hinges <i>new</i>	\$211.00	\$422.00 +
3	1	Rear boot lid emble logo <i>new</i>		\$85.00 -
4	1	Rear Boot Lid RH logo <i>new</i>		\$50.00 -
5	1	Rear Boot Lid Inner Lock <i>new</i>		\$549.10 348
6	1	Rear boot lid inner rubber <i>cut</i>		\$255.00 -
7	1	Rear Boot Lid center moulding <i>new</i>		\$352.00 -
8	2	Rear Boot Lid center moulding side clips <i>new</i>	\$8.50	\$17.00 -
9	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 +
10	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$155.10	\$310.20 +
11	1	Rear Boot Lid Inner Trim board <i>new</i>		\$658.00 485
12	1	Rear boot lid windscreen seal <i>new</i>		\$188.00 -
13	2	Rear Boot Lid side reflector <i>LH new</i>	\$421.20	\$842.40 421.20 277
14	2	tail lamp <i>new</i>	\$725.00	\$1,450.00 X
15	4	tail lamp clips <i>new</i>	\$8.50	\$34.00 +
16	2	tail lamp panel <i>new</i>	\$311.20	\$622.40 +
17	1	Rear End Panel outer <i>Dented</i>		\$740.00 597
18	1	Rear End Panel inner <i>new</i>		\$580.00 +
19	1	Rear End Panel Top Garnish <i>Dented</i>		\$288.20 -
20	1	Rear Bumper <i>Dented</i>		\$1,372.00 688
21	2	Rear Bumper side reflector <i>LH new</i>	\$95.20	\$190.40 95.20
22	?	Rear Bumper Side Bracket <i>new</i>	\$112.10	\$224.20 +
23	1	Rear Bumper reverse sensor <i>new</i>		\$350.00 2nd (sw)
24	2	Rear Bumper Bracket <i>new</i>	\$98.20	\$196.40 +
25	8	Rear bumper clips <i>new</i>	\$6.50	\$52.00 30
26	2	Rear fender inner liner cover <i>new</i>	\$488.00	\$976.00 +
27	2	rear fender inner panel <i>new</i>	\$655.00	\$1,310.00 +
28	1	Rear floor panel top cover <i>new</i>		\$535.77 +
29	1	Rear floor panel sealant <i>new</i>		\$250.00 X
30	1	Rear floor panel inner trim <i>new</i>		\$655.00 +

Subtotal :- \$15,168.07

5035.40

3776.65

Labour charges

To Remove & refix cushion

~~\$120.00~~ 60

To Remove & refix rear exhaust

\$0.00 +

To Remove & refix rear windscreen

~~\$120.00~~ ✓

Gum

~~\$50.00~~ ✓

To Remove & refix reverse Sensor

~~\$120.00~~ 50

To Remove & refix rear camera

~~\$0.00~~ +

Tuff kote

~~\$120.00~~ 60

To Check Wiring System

~~\$80.00~~ 30

Panel beating

~~\$1,000.00~~ 80

Spray painting

~~\$1,000.00~~ 80

Subtotal :- \$2,610.00

Total :- \$17,778.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L;

r/s 16/05/23.

06 Days

total: 5746.55

r/s: 4.6K ✓