

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/05/2023

User ID : munsan

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REMOVE & REFIX FRONT RHS VIEW MIRROR	\$338.00	
O REPAIR FRONT LH PORTION <i>bumper</i>	\$676.00	
total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT BUMPER	\$378.00	
O RESPRAY VIEW MIRROR	\$220.00	
O RESPRAY WHEEL CAP	\$220.00	
O RESPRAY RIM	\$220.00	
total Spray Painting & Panel Beating	\$1,038.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	
O REMOVE AND REFIT TYRE	\$120.00	
O REMOVE AND REFIX UNDERCARRIAGE	\$300.00	
O REPLACE SUNDRY PARTS	\$100.00	
total Other Costs	\$920.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	<i>RC X</i>
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	<i>RC X</i>
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	<i>RC X</i>
		53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	25.00	\$170.85	Replace	<i>RC X</i>
		53852-47041	PAD, FR WHEEL LH	1.00	\$65.00	25.00	\$48.75	Replace	<i>?</i>
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace	<i>?</i>
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	<i>RC ✓</i>
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	<i>X</i>
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	<i>?</i>
		48069-47060	LOWER ARM SUB-ASSY, FRONT LH	1.00	\$823.20	25.00	\$617.40	Replace	<i>?</i>
		48520-80639	ABSORBER SET, SHOCK, FRONT LH	1.00	\$511.40	25.00	\$383.55	Replace	<i>?</i>
		87910-47450	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,556.00	10.00	\$1,400.40	Replace	<i>CD ✓</i>
		87915-47070-A1	COVER, OUTER MIRROR, RH	1.00	\$117.80	25.00	\$88.35	Replace	<i>RC ✓</i>
total					\$7,071.94		\$5,601.45		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHF378J
Case Reference Number	TAX/05/23/2034
Registration Date	12/12/19
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LIM KOK KEONG
Type of Accident	Side Swipe
Accident Date and Time	11/5/23 1:45 PM
Accident Reported Date and Time	11/5/23 2:58 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118398
Special Instruction to ARC, if any	RIGHT SIDE MIRROR
Prepared Date and Time	11/5/23 3:50 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost		\$1,014.00	\$0.00
Total Spray Cost		\$1,038.00	\$0.00
Total Spare Part Cost		\$4,481.16	\$0.00
Total Other Cost		\$920.00	\$0.00
TOTAL COST		\$7,453.16	\$0.00
Jump Sum Total		\$7,450.00	\$0.00
Number of Repair Days		7.0	2 days
Prepared / Adjusted By		Boon Chew Tay	
ARC / Surveyor Sign Off Date		11/05/2023 4:01 PM	
Signature			
Remarks			

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

