

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xin Yu.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 5600 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACKET ?	1	\$ 34.00	✓	sls
(22)	FRONT WHEEL HOUSING LINER - LH <i>torn</i>	1	\$ 198.00	✓	sls
(23)	HEAD LIGHT FOR GAS DISCHARGE LAMP - LH <i>cut</i>	1	\$ 2,975.00	✓	
(24)	LIFT CYLINDER - LH <i>new</i>	1	\$ 223.00	+	
25	LIFT CYLINDER HOSE <i>new</i>	1	\$ 208.00	+	
(26)	LIFT CYLINDER WASH WATER RESERVOIR <i>Rehd</i>	1	\$ 231.00	✓	sls
27	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 22.00	+	
(28)	LOCK CARRIER <i>new could</i>	1	\$ 854.00	✓	sls
29	RADIATOR AIR GUIDE - LH <i>new</i>	1	\$ 36.00	+	
30	RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>	1	\$ 20.00	+	
(31)	READY-MIX COOLANT <i>new</i>	6	\$ 326.00	✓	sls
(32)	FRONT ALUMINIUM RIM - LH <i>cut</i>	1	\$ 1,380.00	✓	
33	FRONT ALUMINIUM RIM RUBBER VALVE <i>new</i>	1	\$ 4.00	+	
(34)	FRONT NUMBER PLATE <i>new</i>	S/N	\$ 60.00	+	
35	SUNDRIES ?		\$ 600.00	?	

TOTAL SPARE PARTS : \$ 14,284.00

TOTAL LABOUR CHARGES : \$ 10,322.00

GRAND TOTAL : \$ 24,606.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 5600 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	X ✓ S.S.
4	TO DISMANLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, AND LHS HEADLIGHT. TO REPAIR BONNET. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	1000 + 1250 S.S.
5	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$ 3,000.00	1100
6	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,322.00	

+3 days

Add 3 days for the replacement of lock carrier

S.S.

Car in mp 19680

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AAA-Adrian
- 5 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 5600 S

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehard</i>	1	\$ 2,515.00	✓
2	FRONT BUMPER FIXING PARTS <i>pen</i>	1	\$ 207.00	+
3	FRONT BUMPER TRIM COVER - LH <i>pen</i>	1	\$ 193.00	✓ <i>sl.s.</i>
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	1	\$ 185.00	?
5	FRONT BUMPER PULL STRAP - LOWER <i>pen</i>	4	\$ 245.00	+
6	FRONT BUMPER GUIDE SECTION - LH <i>cracked</i>	1	\$ 46.00	✓ <i>sl.s.</i>
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>missing</i>	1	\$ 129.00	-
8	RADIATOR GRILLE <i>cracked</i>	1	\$ 813.00	+
9	RADIATOR GRILLE COVER <i>pen</i>	1	\$ 116.00	+
10	CAUTION SIGN STICKER <i>pen</i>	1	\$ 17.00	+
11	AIR CONDITIONER STICKER	1	\$ 9.00	+
12	FRONT BUMPER SIDE REINFORCEMENT <i>pen</i>	1	\$ 896.00	+
13	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 163.00	?
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>pen</i>	1	\$ 67.00	+
15	HORN LOW TONE - LH <i>pen</i>	1	\$ 225.00	+
16	FRONT FENDER - LH <i>Dented</i>	1	\$ 1,012.00	✓
17	FRONT FENDER ATTACHMENT PARTS <i>pen</i>	1	\$ 80.00	X
18	FRONT FENDER BRACKET - CENTER ?	1	\$ 57.00	?
19	FRONT FENDER RIVET <i>pen</i>	6	\$ 24.00	✓
20	FRONT FENDER BRACE <i>Best</i>	1	\$ 114.00	✓ <i>sl.s.</i>
SUB TOTAL SPARE PARTS		:	\$ 7,113.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.