

(08/11/3) Wef

ASS. REC. BY: Marcus

REF:

CC6/A1623004913/Upa3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV5943M

at Workshop m/s

of

Insured: SAG 4748 E

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$ 60k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

903 E

Vehicle: IN / OUT

Date: _____ Person Contacted: L14533330

Veh No: SLV5943M

Yr Regn: 08/01/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Honda Jazz

C.C

1498

Colour: Silver

A/C:

Insured / Std / NI / NA

Sp. Reading: 130660

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK5850JX 202006

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/05/23

D.O.I. 15/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 12k.

23/5/23

NO 31

4/5 \$ 3450

Inland Roy

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0057/05/23
THIRD PARTY CLAIM
M/S : ISHAK BIN YUSOFF
BLK 222 PASIR RIS STREET 21
#02-120 SINGAPORE 510222

Attn :
Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLV5943M - HONDA JAZZ
INSURED : ISHAK BIN YUSOFF
DATE OF ACCIDENT : 14/05/2023
POLICY NO : M0038408

Page : 1/2
Date : 15/05/2023

ENGINE# : D
CHASSIS# : E

not Allowed
see
15/5/23
1/5 # 3450
Today's
Weighted Avg

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 rear windscreen rubber moulding <i>see</i>	1@	28.50	28.50	28.50
2 rear boot <i>body</i>	1@	888.10	888.10	888.10
3 rear boot hinge top L & R <i>11</i>	2@	52.80	52.80	105.60
4 rear jazz emblem <i>see</i>	1@	33.20	33.20	33.20
5 rear boot lock top <i>3er</i>	1@	112.30	112.30	112.30
6 rear boot lock lower catch <i>11</i>	1@	24.70	24.70	24.70
7 rear boot inner finisher <i>De/Torn</i>	1@	242.60		242.60
8 rear lamp assembly RH <i>one</i>	1@	268.40	268.40	268.40
9 rear bumper <i>2</i>	1@	540.20	540.20	540.20
10 rear bumper parking sensor <i>no function</i>	2@	163.80	163.80	327.60
11 rear boot rubber <i>twi</i>	1@	92.30	92.30	92.30
12 rear end panel <i>no 13er</i>	1@	405.10	405.10	405.10
13 rear end panel inner garnish <i>twi</i>	1@	64.80	64.80	64.80
14 rear bumper lower spoiler <i>cut</i>	1@	264.50	264.50	264.50
15 rear bumper side retainer L & R <i>11</i>	2@	19.20	19.20	38.40
16 rear boot plastic handle RH <i>see</i>	1@	19.20	19.20	19.20
				3,212.90
				-642.58
				\$2,570.32

Less 20%

Total Material

Special Nett Items

1 rear windscreen sealant <i>see</i>	1@	40.00	40.00	40.00
				40.00
				0.00
				\$40.00

Total S/Nett

Labour & Misc

1 Remove and install rear windscreen.				150.00
---------------------------------------	--	--	--	--------



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0057/05/23

Page : 2/2
Date : 15/05/2023

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
2 Remove and install rear boot carpet.			60	120.00
3 Remove and install rear boot, rear lamp, rear bumper. Cut out & renew end panel, knocking spare tyre panel & restraighthen body.			600	900.00
4 Spray Painting			820	850.00
5 Check wiring system			20	25.00
6 Reset parking sensor.			50	80.00
				2,125.00

Total Labour

\$2,125.00

Nett Total Before Gst

\$4,735.32

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 32.67.60
201
2614.08
40
1670
4324.08
3454