

Date: 15/05/2023

Vehicle No: SMW6584S

Model: TOYOTA PRIUS 5DR HATCHBACK

Chassis: JTDKB3FU703091278-2020

Reg.Year: 2020

Third Party Insurer: AIG

Third Party Veh No: GBK5515S

Date of Accident: 12/05/223

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT SIDE MIRROR ASSY LH	1		\$1,283.00
2	FRONT SIDE MIRROR COVER LH	1		\$99.00
3	FRONT DOOR LH	1		\$1,249.00
4	FRONT DOOR WINDOW GLASS	1		\$879.00
5	FRONT DOOR OUTER LOWER MOULDING LH	1		\$99.00
6	FRONT DOOR HANDLE LH	1		\$95.00
7	FRONT FENDER LH	1		REPAIR
SUB TOTAL				\$3,704.00
LESS 25%				-\$926.00
PARTS TOTAL				\$2,778.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS	1		\$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$300.00 2001

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, SIDE MIRROR COVER LH & ETC.

\$300.00 2501

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR LH.

\$120.00 601

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 201

LABOUR TOTAL \$800.00

TOTAL \$3,628.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office
8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1010 Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 Fax: (+65) 6481 1011

