

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**12 MAY 2023**

Estimate No. : b1 65976 Page No. : 1 of 4
Date Estimated : 12/05/2023
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Quah Chin Keat
21 JALAN RAJA UDANG #21-05

Singapore 329215

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM779M	WBA70DY0008C20265	25/02/2022	318i Sedan	6080

DESCRIPTIONVALUE

To make good rear bumper.

1,275.00

To painting rear bumper.

1,038.00

To check electrical wiring system and lighting at the rear section for proper function.

177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

177.00

Sundries.

40.00

Total Labour 1: **2,707.00**

Labour 1	:	2,707.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	216.56
Grand Total	:	2,923.56



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **