

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melody Teoh

Date: 30 Jun 2023

Preliminary Advice

Vehicle No	: SMM226T	Accident Date	: 02/05/2023
Make	: BMW X3	Policy No.	: CDMPG23001078
Assignment Date	: 15/05/2023	Excess	: S\$500.00
Date of Inspection	: 16/05/2023	Est. Duration of Repair	: 5
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,252.60	(Estimate \$23,467.70 + Supplementary \$784.90)
Revised Amount	:S\$	11,411.80	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	11,411.80	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	68,501.00
Salvage Value	:S\$	
Margin for Repair	:S\$	89,499.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.