



Final Report

Estimate No. : **b1 65884**
Date Estimated : **05/05/2023**
Prepared By : **Foong Shiuh Jye**

Page No. :

- **ESTIMATE REPAIR FOR** -
Selvaganesan S/O Sivalingam
21 Tampines Central 7
#07-21

- **ACCOUNT** - **136**
Ergo Insurance Pte Ltd
8 Temasek Boulevard
#04-01 Suntec Tower 3
Singapore 038988

Singapore 528608

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SMM226T	WBATR12000LM17670	29/04/2019	X3 sDrive20i	106559

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumpers panel and attachments, trunk lid and attachments include carrying out necessary repairs caused by the accident	1,700.00		1,700.00
To spray paint rear bumper and boot lid	1,972.00		1,972.00
To remove and install rear windscreen glass to facilitate repairs	574.00		574.00
To conduct water leak tests	75.00		75.00
To carry out body cavity preservation (Per panel)	112.00		112.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function	168.00		168.00
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	504.00		504.00
To check electrical wiring system and lightings at the rear section for proper function	168.00		168.00
Sundries	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TRUNK LID	2,112.45	1.00	0.00	2,112.45
REAR BUMPER PANEL PRIMED (M/PMA)	1,536.45	1.00	0.00	1,536.45
REAR BUMPER BOTTOM TRIM PANEL (M)	365.85	1.00	0.00	365.85

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W





Final Report

# PLAQUE 82MM	72.85	1.00	0.00	72.85
# LETTERING X3	65.60	1.00	0.00	65.60
# LETTERING S DRIVE 20i	98.35	1.00	0.00	98.35
# HOOK AND LOOP FASTENER	2.60	10.00	0.00	26.00
# EXPANDING RIVET BLACK	1.40	10.00	0.00	14.00
REAR LH LIGHT IN THE TRUNK LID	428.45	1.00	0.00	428.45
REAR RH LIGHT IN THE TRUNK LID	428.45	1.00	0.00	428.45
# ULTRASONIC SENSOR BLACK	254.05	2.00	0.00	508.10
DECOUPING RING PDC TORQUE CONVERTER	5.30	2.00	0.00	10.60
(DG) CLEANER R1 (100ML)	30.05	1.00	0.00	30.05
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0.00	263.10
(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	28.50	1.00	0.00	28.50

SUPPLEMENTARY ITEMS

Total Labour :	5,423.00
Total Parts :	5,988.80
Total Labour & Parts (before GST) :	11,411.80
Deduction for Excess :	500.00
Total Repair Costs less Excess:	10,911.80
GST @8%:	872.94
Grand Total :	11,784.74

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

