

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 65884**
Date Estimated : **05/05/2023**
Prepared By : **Foong Shiuh Jye**

Page No. : **1 of 5**

- ESTIMATE REPAIR FOR -
Selvaganesan S/O Sivalingam
21 Tampines Central 7
#07-21

Singapore 528608

- ACCOUNT - 136
Ergo Insurance Pte Ltd
8 Temasek Boulevard
#04-01 Suntec Tower 3
Singapore 038988

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM226T	WBATR12000LM17670	29/04/2019	X3 sDrive20i	96631

DESCRIPTION

VALUE

To replace bumper rear panel, boot lid, tail end panel and interior tail trim

1700 5,950.00

To spray paint bumper rear panel, boot lid, tail end panel and interior tail trim

1972 3,562.00

To replace rear windscreen glass.

574.00

To conduct water leak tests.

75.00

To supply and install rear windscreen solar film.

Xnn ? 531.00

To carry out body cavity preservation.
(Per panel).

112 118.00

To carry out body cavity preservation.
(For cut panel).

Xnn ? 504 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

508 531.00

To replace bootlid smart opener control unit, top and bottom sensor line including program and conduct check for proper function.

Xnn 627? 661.00

To replace rear PDC sensor wire harness including reset and conduct check for proper function.

Xnn 252? 266.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2-0020081-X

ESTIMATE

LKK Auto Complaints hereby notify
the Repairer of the following:

- To reserve before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate No. : b1 65884
Date Estimated : 05/05/2023
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO. CHASSIS NO. REGN. DATE
SMM226T WBATR12000LM17670 29/04/2019

Acknowledged by Repairer
MODEL
Signature:
Date: sDrive20i

MILEAGE
96631

DESCRIPTION

Sundries. *ncc*

VALUE

150.00

Total Labour 1: 13,303.00

DESCRIPTION	QTY	PRIC	VALUE
TAIL PANEL <i>1. Xan</i>	1	558.45	558.45
INTERIOR TAIL TRIM PANEL <i>1. Xan</i>	1	488.15	488.15
TRUNK LID <i>1. Xan</i>	1	2,112.45	2,112.45
REAR BUMPER CARRIER <i>1. Xan</i>	1	800.10	800.10
LH SIDE GUIDE FOR BUMPER <i>1. Xan</i>	1	136.30	136.30
RH SIDE GUIDE FOR BUMPER <i>1. Xan</i>	1	136.30	136.30
LH BUMPER GUIDE <i>1. Xan</i>	1	175.25	175.25
RH BUMPER GUIDE <i>1. Xan</i>	1	175.25	175.25
REAR BUMPER BOTTOM REINFORCEMENT <i>1. Xan</i>	1	124.55	124.55
REAR BUMPER TOWING LUG COVER (M) <i>1. Xan</i>	1	79.10	79.10
REAR BUMPER PANEL PRIMED (M/PMA) <i>1. Xan</i>	1	1,536.45	1,536.45
SET MOUNTING PDC/PMA SENSOR REAR(M) <i>1. Xan</i>	1	138.65	138.65
REAR BUMPER BOTTOM TRIM PANEL (M) <i>1. Xan</i>	1	365.85	365.85
BUMP STOP <i>1. Xan</i>	10	3.45	34.50
REAR SILENCER HEAT INSULATION <i>1. Xan</i>	1	80.75	80.75
REAR LH LIGHT IN THE SIDE PANEL <i>1. Xan</i>	1	612.05	612.05
REAR RH LIGHT IN THE SIDE PANEL <i>1. Xan</i>	1	612.05	612.05
REAR LH LIGHT IN THE TRUNK LID <i>1. Xan</i>	1	428.45	428.45
REAR RH LIGHT IN THE TRUNK LID <i>1. Xan</i>	1	428.45	428.45
DECOUPLING RING PDC TORQUE CONVERTER <i>1. Xan</i>	2	5.30	10.60
ULTRASONIC SENSOR ALPINWEISS (U300) <i>1. Xan</i>	1	386.00	772.00
SET ADHESIVE PADS FOR ACE 2.0 <i>1. Xan</i>	1	37.35	37.35
(DG) CLEANER R1 (100ML) <i>1. Xan</i>	1	30.05	30.05
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>1. Xan</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>1. Xan</i>	1	28.50	28.50

Total Parts : 10,164.70

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Reg. No. Claim No.

Date & Time 16/05/23 01450 Excess \$ TBA

Surveyor's Name Reason Sign Jm PERENT

Surveyor's Tel 96016068 Authorised Yes/No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PML Yes/No

Surveyor's E-mail

No. of Working Days Recommend 5 days

Resy before put

Labour 1	:	13,303.00
Parts	:	10,164.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	1,877.42
Grand Total	:	25,345.12



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **