



Motor Claim Department  
Lonpac insurance Bhd  
300, Beach Road,  
7 The Concourse, #17-04,  
Singapore 199555

[customer\\_sg@lonpac.com](mailto:customer_sg@lonpac.com)

15-May-23

Dear Sir / Madam

**Re: Maserati Quattroporte GTS V8, Vehicle Reg No, SKA8168L , Chassis No, ZAMPP56C001095624**

We are pleased to submit quotation for the repair of the above-mentioned vehicle:

<b><u>A) Labour Description</u></b>	<b><u>Labour Cost</u></b>
1 Renew rear rocket panel, both tail lamp housing include cut, weld & reshape luggage compartment floor panel.	\$ 3,800.00
2 Reshape luggage compartment floor panel.	\$ 1,200.00
3 Set up vehicle on the car jig to facilitate body repair.	\$ 1,800.00
4 Remove & reinstall, both tail lamp, rear bumper, luggage compartment carpet finishing, spare wheel compartment, heat shield, both wheel arch	\$ 3,500.00
5 cover and electronic handbrake system both exhaust to facilitate repair	
6 Remove & renew rear bumper, parking sensor, sensor harness	\$ 2,100.00
7 Remove & Renew boot cover include alignment transfer wiring harness, locking device.	\$ 1,500.00
8 Respray primer & paint to body colour rear bumper, rear bumper sensor rear rocket panel and luggage compartment floor panel both rear fender & boot cover	\$ 6,800.00
9 Perform All Wheel Alignment .	\$ 450.00
10 Reset all system with SD3 computer tester.	\$ 1,500.00

<b><u>B) Parts</u></b>	<b><u>Qty</u></b>	
1 REAR BUMPER	1	\$ 4,074.00
2 CENTRAL LOWER TRIM - DIABOLIK BLACK	1	\$ 175.90
3 LEFT REAR BUMPER LOWER TRIM - DIABOLIK BLACK	1	\$ 412.00
4 RIGHT REAR BUMPER LOWER TRIM - DIABOLIK BLACK	1	\$ 412.00
5 UNDER-TAILLIGHT LH BRACKET	1	\$ 70.00
6 UNDER-TAILLIGHT RH BRACKET	1	\$ 70.00
7 RH BUMPER MOUNTING BRACKET	1	\$ 113.08
8 LH BUMPER MOUNTING BRACKET	1	\$ 113.08
9 UPPER CENTRAL BRACKET	1	\$ 201.90
10 REAR BUMPER SHOCK ABSORBER	1	\$ 339.05
11 Rivet(FOR CENTREL BRACKET )	12	\$ 14.00

12 RIVET (BETWEEN BUMPER AND CENTER TRIM)	4	\$	14.00
13 Parking Sensor	2	\$	453.90
14 Parking Sensor RING	2	\$	34.70
15 LH EXTERNAL PARKING SENSOR SLEEVE - BLACK	1	\$	122.55
16 LH INTERNAL PARKING SENSOR SLEEVE - BLACK	1	\$	122.55
17 RH EXTERNAL PARKING SENSOR SLEEVE - BLACK	1	\$	122.55
18 RH INTERNAL PARKING SENSOR SLEEVE - BLACK	1	\$	122.55
19 BOOT LID	1	\$	7,407.80
20 Boot lining	1	\$	290.00
21 Both boot locking devise	1	\$	199.23
22 Boot weather seal.	1	\$	505.75
23 Boot chrome moulding with reg plate lamps	1	\$	1,341.25
24 Maserati emblem	1	\$	227.60
25 QP emblem	1	\$	227.60
26 Parking sensor cable	1	\$	174.28
27 Inner luggage compartment plastic covers and clip / plugs			TBA
28 boot both antivibration pad / stopper			TBA
29 Third Brake Lamp Assy	1		TBA
30 Boot button	1	\$	37.95
31 Boot plug	1	\$	32.45
32 Boot locking device striker	1	\$	48.90
33 RH Lateral Trident (GTS	1	\$	55.85
34 LH Lateral Trident (GTS)	1	\$	55.85
35 Rh rear lamp Mobile Side	1	\$	1,487.23
36 RH Rear Light Fixed Side	1	\$	1,475.75
37 LH Rear Light Fixed Side	1	\$	1,475.75
38 Lh Rear Lamp Mobile Side.	1	\$	1,475.75
39 Boot right cable guide outer cover	1	\$	71.43
40 Boot left cable guide outer cover	1	\$	71.43
41 MISCELLANEOUS.	1	\$	120.00
42 REAR REG NO,PLATE.	1	\$	30.00

<b>TOTAL:</b>			<b>\$ 22,650.00</b>
---------------	--	--	---------------------

<b>Total Labour</b>	:	<b>\$ 22,650.00</b>
<b>Total Parts</b>	:	<b>\$ 23,799.63</b>
		<b>\$ 46,449.63</b>
<b>Plus 7% GST</b>	:	<b>\$ 3,251.47</b>
<b>Grand Total</b>	:	<b>\$ 49,701.10</b>

Should this repair job require any additional parts, we will inform you and bill you accordingly. Please confirm your acceptance of this quotation by sending us a return fax with your signature and company stamp on it.

Yours sincerely,

I agree and accept the above

Hong Seh Motors Pte Ltd

Workshop Department

Signature & Company stamp