

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9010 8488 / Email: claims@carsmith.biz

VEHICLE NO: SLJ5167A

MAKE & MODEL: HONDA STREAM

DOA: 17.04.2023

CLAIM TYPE: TP CLAIM

not allowed
her
16/5/23

3 days. 2/5 = 2200
Telukhok After. rep.

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BUMPER	1	\$ 960.90	DO/OE ✓
REAR BUMPER SIDE RETAINER	2	\$ 174.00	1er ✓
REAR BUMPER BRACKET	2	\$ 174.00	11 X
REAR BUMPER TOW GARNISH	1	\$ 42.50	11 X
REAR BUMPER TOWING COVER	1	\$ 34.70	11 X
REAR BUMPER LOWER GARNISH	1	\$ 480.00	NS X
REAR BUMPER REFLECTOR	2	\$ 272.40	NS X
TAILLAMP LH	1	\$ 362.50	11 X
TAILLAMP RH	1	\$ 362.50	11 X
BOOTLID 7eilsote 903.20	1	\$ 1,175.00	DO ✓
BOOTLID PANEL	1	\$ 997.60	Replaced X
BOOTLID INNER TRIMBOARD	1	\$ 425.60	11 X
BOOTLID OUTER GARNISH	1	\$ 195.80	11 X
BOOTLID LOGO	1	\$ 85.80	11 X
BOOTLID INNER LOCK	1	\$ 178.60	8u X
BOOTLID WIPER MOTOR	1	\$ 386.40	11 X
BOOTLID HINGE	2	\$ 272.40	11 X
BOOTLID EMBLEM 'STREAM'	1	\$ 85.80	1er ✓
EXHAUST PIPE	1	\$ 1,050.00	11 X
REAR END PANEL INNER	1	\$ 258.60	11 X
REAR END PANEL OUTER	1	\$ 386.70	11 X
REAR END PANEL TOP GARNISH	1	\$ 226.70	11 X
REAR FLOOR PANEL	1	\$ 985.40	11 X
REAR SPARE TYRE BRACKET	1	\$ 225.80	11 X
		\$ 9,799.70	
	LESS 20%	\$ 1,959.94	
	SUB TOTAL	\$ 7,839.76	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
SUNDRIES	1	\$ 50.00	11 X
REAR BUMPER CLIPS	1 SET	\$ 80.00	11 30
REVERSE SENSOR WITH MODULE	1	\$ 280.00	not broken 200
BOOTLID INNER TRIMBOARD CLIPS	1	\$ 55.00	11 X
BOOTLID SEALANT	1	\$ 100.00	11 X
REAR END PANEL TOP GARNISH CLIPS	1 SET	\$ 80.00	11 X
REAR END PANEL SEALANT	1	\$ 80.00	11 X
	SUB TOTAL	\$ 725.00	

LABOUR	QTY	PRICE (\$)	REMARKS
TO DISMANTLE / RENEW THE REAR ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.	1	\$ 1,200.00	400

TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR	1	\$ 200.00	14 X
TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	1	\$ 80.00	20
TO REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE	1	\$ 100.00	60
TO REMOVE AND REFIT TAILGATE WINDSCREEN TO FACILITATE THE REPAIR	1	\$ 180.00	120
TO REMOVE AND REFIT EXHAUST PIPE TO FACILITATE THE REPAIR	1	\$ 200.00	11 X
TO MEASURE, DRILL HOLES ON REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS	1	\$ 80.00	11 X
TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	1	\$ 200.00	30
SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY TAILGATE, REAR BUMPER, REAR END PANEL, REAL FLOOR PANEL AND OTHER AFFECTED AREA / PANEL	1	\$ 1,200.00	600

SUB TOTAL \$ 3,440.00

GRAND TOTAL \$ 12,004.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1679.2
202
1343.36
230
1230
2803.36
202
2242.