

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SND8508M

Make & Model: Toyota Esquire Hybrid

Chassis number: ZWR800512879

Vernon

No.	Description of spare parts	Qty	Amount S\$	
1	Tailgate <i>BUK</i>	1	\$ 1,919.30	1800
2	Tailgate centre moulding <i>X</i>	1	\$ 895.40	X NW
3	Tailgate centre moulding emblem <i>X</i>	1	\$ 71.60	X NW
4	Tailgate RH chrome moulding <i>X</i>	1	\$ 445.10	X NW
5	Tailgate LH chrome moulding <i>CRG</i>	1	\$ 445.10	300
6	Tailgate "ESQUIRE" emblem <i>MEC</i>	1	\$ 93.20	/
7	Tailgate "Hybrid" emblem <i>MEC</i>	1	\$ 60.80	/
8	Tailgate windscreen glass RH rubber moulding <i>MEC</i>	1	\$ 72.80	/
9	Tailgate windscreen glass LH rubber moulding <i>MEC</i>	1	\$ 72.80	/
10	Tailgate lock <i>CRG</i>	1	\$ 495.00	350
11	Tailgate inner trim board <i>CRG</i>	1	\$ 605.10	570
12	Tailgate inner trim board clips <i>MEC</i>	1set	\$ 80.00	50
13	Tailgate weatherstrip <i>X Deform</i>	1	\$ 395.10	280
14	Tailgate inner pull handle <i>X</i>	1	\$ 44.10	X NW
15	Tailgate RH rubber stopper <i>X</i>	1	\$ 23.70	X NW
16	Tailgate LH rubber stopper <i>missing</i>	1	\$ 23.70	/
17	Tailgate RH damper <i>X</i>	1	\$ 1315	X NW
18	Tailgate LH damper <i>X</i>	1	\$ 1315	X NW
19	Rear bumper <i>CRG</i>	1	\$ 573.80	/
20	Rear bumper clips <i>MEC</i>	1set	\$ 80.00	50
21	Rear bumper tow cover <i>X</i>	1	\$ 55.60	NW
22	Rear bumper RH side upper cover <i>X</i>	1	\$ 187.80	NW
23	Rear bumper RH side upper cover retainer <i>X</i>	1	\$ 170.60	NW
24	Rear bumper LH side upper cover <i>CRG</i>	1	\$ 187.80	/
25	Rear bumper LH side upper cover retainer <i>X</i>	1	\$ 170.60	X
26	Rear bumper RH reflector <i>X</i>	1	\$ 64.50	X
27	Rear bumper LH reflector <i>X</i>	1	\$ 64.50	X
28	Rear bumper RH retainer <i>X</i>	1	\$ 86.10	X
29	Rear bumper LH retainer <i>X</i>	1	\$ 86.10	X
30	RH taillamp assy <i>X</i>	1	\$ 1,446.80	X NW
31	RH taillamp panel <i>X</i>	1	\$ 243.10	X
32	RH taillamp lock clips <i>X</i>	1	\$ 80.00	X
33	LH taillamp assy <i>X</i>	1	\$ 1,446.80	X NW
34	LH taillamp panel <i>X</i>	1	\$ 243.10	X
35	LH taillamp lock clips <i>X</i>	1	\$ 80.00	X
36	End panel <i>pent</i>	1	\$ 779.40	650
37	End panel inner garnish <i>CRG</i>	1	\$ 175.40	145
38	End panel inner garnish clips <i>MEC</i>	1set	\$ 70.00	50
39	Rear antenna sensor <i>CRG</i>	1	\$ 198.30	165
40	Rear antenna sensor wire harness <i>X</i>	1	\$ 205.70	X NW
41	Rear compartment panel top board cover <i>CRG</i>	1	\$ 598.70	/

42	Rear compartment panel inner carpet mat X NN	1	\$	469.70	
43	Rear compartment panel inner carpet mat clips X NN	1set	\$	95.00	
44	Rear jack panel X NN	1	\$	111.40	
45	Rear RH fender inner aircon blower X NN	1	\$	1,550.40	
46	Rear RH fender inner trim board X NN	1	\$	621.50	
47	Rear RH fender inner trim board clips X NN	1set	\$	80.00	
48	Rear LH fender inner trim board X NN	1	\$	621.50	580
49	Rear LH fender inner trim board clips X NN	1set	\$	80.00	50
50	Rear battery cover X NN	1	\$	289.70	
51	Rear 3rd seat cushion RH leg cover X NN	1	\$	189.90	
52	Rear 3rd seat cushion LH leg cover X NN	1	\$	189.90	

\$ 18,020.70
 Parts less 25% \$ 4,505.18
 Total: \$ 13,515.53

No.	Special Nett Items	Qty	Amount S\$	
1	Rear bumper reverse sensor Faulty	1set	\$ 350.00	200
2	End panel joint sealant NEC	1	\$ 80.00	40
3	Tailgate windscreen glass sealant NEC	1	\$ 80.00	60
4	Tailgate windscreen glass inner seal NEC	1	\$ 60.00	40
5	Tailgate reverse camera X NN	1	\$ 750.00	
6	Rear number plate X NN	1	\$ 80.00	
Total:			\$ 1,400.00	340

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 600 1,500.00
2	Spray painting on affected areas and panels	\$ 600 1,300.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 100.00
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 80 280.00
6	Remove and replace tailgate reverse camera to assist repair	\$ 30 100.00
7	Remove and replace tailgate inner mechanism to new tailgate	\$ 60 180.00
8	Remove and replace rear bumper reverse sensors to assist repair	\$ 30 100.00
9	Remove and replace rear inner trims and garnish to assist repair	\$ 40 400.00

1500

Total: \$ 2,540.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 13,515.53

Special Nett: \$ 1,400.00

Labour: \$ 2,540.00

Total Amount: \$ 17,455.53

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5 days

L19

2pm 8/10/23

16/5/23